

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B2658 - 2014 F150 CREWCAB										
29-May-2014	26	0	159611	14-002-063	Install Computer Stand / Dock	29-May-2014 17:00:38	BDETL	C	DON	327.56
29-May-2014	26	0	159611	14-034-006	Install Warning Lamps - Special Application	29-May-2014 16:06:16	BDETL	C	DON	375.84
29-May-2014	26	0	159611	14-052-003	Install Radio Equipment	29-May-2014 17:00:29	BDETL	C	DON	1,050.08
29-May-2014	26	0	159611	14-052-011	Install Auxiliary Power	29-May-2014 11:30:44	BDETL	C	DON	141.74
29-May-2014	26	0	159611	14-052-014	Install Cellular Telephone Accessories	29-May-2014 14:07:11	BDETL	C	DON	59.44
29-May-2014	26	0	159611	14-053-005	Install Markings - Vehicle - Decals	29-May-2014 13:39:11	BDETL	C	DON	72.96
29-May-2014	26	0	159611	14-053-014	Install Floor Mats	29-May-2014 16:13:23	BDETL	C	DON	77.03
29-May-2014	26	0	159611	14-071-011	Install Scuff Liner / Bed Mat	29-May-2014 12:14:35	BDETL	C	DON	96.91
29-May-2014	26	0	159611	14-078-009	Install Mud Flaps and Hanger Brackets	29-May-2014 13:50:10	BDETL	C	DON	80.54
29-May-2014	26	0	159611	14-078-014	Install Tarpaulin/ Tonneau Cover	29-May-2014 13:29:04	BDETL	C	DON	422.40
29-May-2014	26	0	159611	06-100-009	Inspect Safety Check	30-May-2014 07:43:35	BTRUCK	P	DON	21.16
25-Sep-2015	0	26	216208	03-002-024	Replace Glass / Windshield	25-Sep-2015 00:00:00	MPNFLD	E	DON	317.23
23-Oct-2015	1	37,995	0	219403	Repair Cooling System	06-Nov-2015 06:39:07	BVLOFC	O	CAN	0.00
23-Oct-2015	1	37,995	0	219403	Inspect A PMI	06-Nov-2015 06:39:07	BVLOFC	P	DON	59.23
06-Nov-2015	0	41,095	0	235991	Replace Ignition System	06-Nov-2015 06:46:40	BVLOFC	O	DON	71.22
29-Mar-2016	0	56,785	0	239386	Replace Front Brakes & Drums	30-Mar-2016 07:43:54	MPNFLD	O	DON	242.28
29-Mar-2016	0	56,785	0	239386	Replace Filter - Inner	30-Mar-2016 07:43:54	MPNFLD	O	DON	15.21
08-Jul-2016	12	56,785	0	251213	Replace Tire - Pneumatic	08-Jul-2016 12:30:10	BTIRE	N	DON	1,233.01
30-Aug-2016	1	73,924	0	257668	Replace Battery	30-Aug-2016 15:28:31	BVLOFC	I	DON	980.99
31-Aug-2016	0	75,299	0	257787	Repair Transceiver - GPS Tracker	21-Sep-2016 15:28:10	BTRUCK	Q	DON	51.27
31-Jan-2017	0	78,593	0	275525	Replace Battery	31-Jan-2017 14:54:27	MONSHP	I	DON	140.99
31-Jan-2017	0	78,593	0	275525	Install Power Inverter/Converter	03-Mar-2017 15:22:57	MONSHP	O	DON	806.33
31-Jan-2017	0	78,593	0	275525	Repair Glass / Windshield	01-Mar-2017 08:07:50	MONSHP	O	DON	50.27
20-Feb-2017	1	78,547	0	277964	Replace Emission Controls	27-Feb-2017 05:57:23	BVLOFC	O	DON	250.68
20-Feb-2017	1	78,547	0	277964	Inspect A PMI	27-Feb-2017 05:58:46	BVLOFC	P	DON	44.35
20-Feb-2017	1	78,547	0	277964	Align All Axles	27-Feb-2017 05:53:53	BVLOFC	I	DON	359.34
20-Feb-2017	1	78,547	0	277964	Repair Power Plant	27-Feb-2017 05:55:32	BVLOFC	O	DON	1,954.78
13-Mar-2017	0	79,275	0	280734	Install Mud Flaps and Hanger Brackets	14-Mar-2017 10:35:17	BTRUCK	O	DON	25.17
13-Mar-2017	0	79,275	0	280734	Replace Rear Brakes & Drums	14-Mar-2017 09:50:03	BTRUCK	I	DON	115.74

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B2658 - 2014 F150 CREWCAB										
13-Mar-2017 0	79,275	0	280734	03-013-037	Replace Caliper - Front	14-Mar-2017 14:41:53	BTRUCK	I	DON	216.84
13-Mar-2017 0	79,275	0	280734	24-017-010	Repair Sensor - Air Pressure	14-Mar-2017 10:17:24	BTRUCK	I	DON	24.68
13-Mar-2017 0	79,275	0	280734	38-045	Service Power Plant	14-Mar-2017 13:23:21	BTRUCK	P	DON	62.43
13-Mar-2017 0	79,275	0	280734	06-100-PMB	Inspect B PMI	14-Mar-2017 15:22:05	BTRUCK	P	DON	22.37
13-Mar-2017 0	79,275	0	280734	03-002-035	Replace Windshield Wiper & Washer	14-Mar-2017 15:50:30	BTRUCK	I	DON	38.55
13-Mar-2017 0	79,275	0	280734	03-034-002	Replace Stop, Tail, Turn & License	14-Mar-2017 16:00:09	BTRUCK	I	DON	65.17
13-Mar-2017 0	79,275	0	280734	03-013-001	Replace Front Brakes & Drums	14-Mar-2017 12:00:11	BTRUCK	O	DON	305.61
03-Apr-2017 0	80,938	0	284265	19-034-023	Wire/Rewire Harness - Rear	08-Apr-2017 07:32:05	NBSHP	O	DON	97.44
17-Apr-2017 1	81,985	0	285460	06-100-PMA	Inspect A PMI	17-Apr-2017 11:51:50	BVLOFC	P	DON	56.86
06-Jul-2017 07	85,907	0	308206	38-100-PMA	Service A PMI	06-Jul-2017 07:44:00	BVLOFC	P	DON	92.05
10-Jul-2017 07	85,907	0	296149	03-002-035	Replace Windshield Wiper & Washer	10-Jul-2017 15:00:00	NBSHP	O	DON	22.24
12-Sep-2017 1	90,543	0	310326	06-100-PMA	Inspect A PMI	12-Sep-2017 12:36:00	BVLOFC	P	DON	53.64
08-Nov-2017 1	99,676	0	311897	06-100-PMA	Inspect A PMI	08-Nov-2017 14:24:57	MONSUP	P	DON	3.02
15-Dec-2017 0	103,707	0	320223	06-100-PMA	Inspect A PMI	15-Dec-2017 08:00:00	BVLOFC	P	DON	58.47
18-Apr-2018 1	110,407	0	331976	03-034-010	Replace Socket - Trailer Light Cord	20-Apr-2018 17:00:48	BTRUCK	I	DON	61.72
18-Apr-2018 1	110,407	0	331976	24-049-001	Repair ECM Fault Code	24-Apr-2018 12:33:28	BTRUCK	I	DON	233.86
18-Apr-2018 1	110,407	0	331976	24-002-024	Repair Glass / Windshield	24-Apr-2018 12:24:13	BTRUCK	I	DON	51.83
18-Apr-2018 1	110,407	0	331976	24-013	Repair Brakes	20-Apr-2018 16:35:00	BTRUCK	I	DON	351.57
18-Apr-2018 1	110,407	0	331976	06-100-009	Inspect Safety Check	20-Apr-2018 09:42:01	BTRUCK	B	DON	136.71
18-Apr-2018 1	110,407	0	331976	03-032-001	Replace Battery	18-Apr-2018 16:28:54	BTRUCK	I	DON	119.60
18-Apr-2018 1	110,407	0	331976	03-002-035	Replace Windshield Wiper & Washer	20-Apr-2018 11:33:28	BTRUCK	I	DON	34.83
18-Apr-2018 1	110,407	0	331976	06-042-012	Inspect Clamps and Hoses		BTRUCK	I	CAN	0.00
18-Apr-2018 1	110,407	0	331976	06-100-PMB	Inspect B PMI	20-Apr-2018 10:47:39	BTRUCK	P	DON	36.53
18-Apr-2018 1	110,407	0	331976	38-045	Service Power Plant	20-Apr-2018 11:12:08	BTRUCK	P	DON	44.61
18-Apr-2018 1	110,407	0	331976	02-002	Clean Cab & Sheet Metal	02-May-2018 09:34:31	BSETUP	J	DON	339.52
28-Apr-2020 1	139,493	0	438306	03-002-024	Replace Glass / Windshield	01-May-2020 16:04:32	BTRUCK	I	DON	294.25
28-Apr-2020 1	139,493	0	438306	03-002-035	Replace Windshield Wiper & Washer	28-Apr-2020 14:38:14	BTRUCK	I	DON	37.06
28-Apr-2020 1	139,493	0	438306	03-013-002	Replace Rear Brakes & Drums	29-Apr-2020 06:57:04	BTRUCK	I	DON	317.16
28-Apr-2020 1	139,493	0	438306	03-017-001	Replace Tire - Pneumatic	30-Apr-2020 11:54:38	BTIRE	I	DON	893.88

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B2658 - 2014 FI50 CREWCAB										
28-Apr-2020 1	139,493	0	438306	03-034-003	Replace Signal, Parking, Backup Lamps	28-Apr-2020 15:43:56	BTRUCK	I	DON	129.84
28-Apr-2020 1	139,493	0	438306	03-034-004	Replace Clearance & Marker Lamps	05-May-2020 07:02:27	BTRUCK	I	DON	46.06
28-Apr-2020 1	139,493	0	438306	03-053-016	Replace Cover - Seat	07-May-2020 07:43:03	BTRUCK	I	DON	156.38
28-Apr-2020 1	139,493	0	438306	06-100-009	Inspect Safety Check	28-Apr-2020 13:38:10	BTRUCK	P	DON	78.99
28-Apr-2020 1	139,493	0	438306	06-100-PMB	Inspect B PMI	07-May-2020 08:14:24	BTRUCK	P	DON	17.20
28-Apr-2020 1	139,493	0	438306	14-034-008	Install Trailer Light Cord	29-Apr-2020 08:00:31	BTRUCK	I	DON	69.86
28-Apr-2020 1	139,493	0	438306	24-021-106	Repair Axle Controls - Electric Shift	01-May-2020 17:02:46	BTRUCK	I	DON	55.26
28-Apr-2020 1	139,493	0	438306	24-022-003	Repair Differential Carrier	28-Apr-2020 15:19:54	BTRUCK	I	DON	68.46
28-Apr-2020 1	139,493	0	438306	38-045	Service Power Plant	28-Apr-2020 14:09:28	BTRUCK	I	DON	49.35
18-May-2020 1	139,503	0	441216	02-002	Clean Cab & Sheet Metal	19-May-2020 12:54:45	BSETUP	I	DON	233.51
18-May-2020 1	139,503	0	441216	24-045-021	Repair Electronic Engine Controls	26-May-2020 12:01:25	BTRUCK	O	DON	90.50
28-May-2020 1		0	442627	02-002	Clean Cab & Sheet Metal	28-May-2020 12:11:20	WTNSHP	Q	DON	67.15
04-Jun-2020 06		0	443676	03-032-001	Replace Battery	04-Jun-2020 07:24:12	WTNSHP	I	DON	171.35
14-Jul-2020 06		0	450355	02-002-011	Clean Cab Accessories - Interior	14-Jul-2020 12:55:33	WTNSHP	P	DON	66.81
21-Jul-2020 14	143,522	0	451772	02-002	Clean Cab & Sheet Metal	29-Jul-2020 16:00:36	BSETUP	I	DON	228.15
21-Jul-2020 14	143,522	0	451772	03-002-015	Replace Quarter & Deck Panels - Rear	28-Jul-2020 14:08:56	BBODY	K	DON	820.44
21-Jul-2020 14	143,522	0	451772	03-002-035	Replace Windshield Wiper & Washer	22-Jul-2020 13:28:01	BTRUCK	I	DON	17.84
21-Jul-2020 14	143,522	0	451772	03-016-002	Replace Chassis Spring - Front	22-Jul-2020 13:04:49	BTRUCK	I	DON	501.00
21-Jul-2020 14	143,522	0	451772	03-045-026	Replace Tensioner - Engine Belts	22-Jul-2020 08:47:41	BTRUCK	I	DON	283.70
21-Jul-2020 14	143,522	0	451772	06-100-009	Inspect Safety Check	21-Jul-2020 15:59:18	BTRUCK	P	DON	71.95
21-Jul-2020 14	143,522	0	451772	06-100-PMB	Inspect B PMI	22-Jul-2020 15:15:41	BTRUCK	P	DON	52.01
21-Jul-2020 14	143,522	0	451772	12-002-015	Refinish Quarter & Deck Panels - Rear	29-Jul-2020 08:41:13	BBODY	K	DON	285.83
21-Jul-2020 14	143,522	0	451772	24-016-004	Repair Stabilizer (Sway) Bar - Front	22-Jul-2020 13:24:33	BTRUCK	I	DON	106.78
21-Jul-2020 14	143,522	0	451772	24-021-103	Repair Differential Carrier	22-Jul-2020 10:55:52	BTRUCK	I	DON	173.82
21-Jul-2020 14	143,522	0	451772	38-045	Service Power Plant	22-Jul-2020 14:13:08	BTRUCK	P	DON	47.96
13-Nov-2020 1	146,784	0	471998	02-002	Clean Cab & Sheet Metal	18-Nov-2020 09:46:28	BSETUP	N	DON	175.90
13-Nov-2020 1	146,784	0	471998	03-002-035	Replace Windshield Wiper & Washer	16-Nov-2020 06:22:49	BTRUCK	N	DON	37.97
13-Nov-2020 1	146,784	0	471998	03-027-038	Replace Electronic Controls, Transmission, Aut	19-Nov-2020 06:26:48	BTRUCK	I	DON	473.41
13-Nov-2020 1	146,784	0	471998	03-032-001	Replace Battery	16-Nov-2020 07:15:22	BTRUCK	N	DON	125.76

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B2658 - 2014 F150 CREWCAB										
13-Nov-2020	1	146,784	0	471998	03-034-001	Replace Headlamps / Fog Lamps	BTRUCK	N	DON	72.02
13-Nov-2020	1	146,784	0	471998	06-100-009	Inspect Safety Check	BTRUCK	P	DON	49.69
13-Nov-2020	1	146,784	0	471998	06-100-PMB	Inspect B PMI	BTRUCK	P	DON	50.00
13-Nov-2020	1	146,784	0	471998	24-042-012	Repair Clamps and Hoses	BTRUCK	I	DON	116.24
13-Nov-2020	1	146,784	0	471998	38-045	Service Power Plant	BTRUCK	P	DON	55.68
02-Mar-2021	0	162,589	0	491329	06-100-PMA	Inspect A PMI	BVLOFC	P	DON	0.00
02-Mar-2021	0	162,589	0	491329	38-100-PMA	Service A PMI	BVLOFC	P	DON	71.91
02-Apr-2021	1	163,898	0	498295	03-002-035	Replace Windshield Wiper & Washer	BTRUCK	I	DON	19.05
02-Apr-2021	1	163,898	0	498295	03-032-002	Replace Starter	BTRUCK	I	DON	216.43
02-Apr-2021	1	163,898	0	498295	06-100-009	Inspect Safety Check	BTRUCK	P	DON	73.33
02-Apr-2021	1	163,898	0	498295	06-100-DOT	Inspect DOT Federal Inspection	BTRUCK	P	DON	27.72
02-Apr-2021	1	163,898	0	498295	06-100-PMB	Inspect B PMI	BTRUCK	P	DON	28.89
02-Apr-2021	1	163,898	0	498295	14-051-006	Install Safety Devices	BTRUCK	Q	DON	42.90
02-Apr-2021	1	163,898	0	498295	14-051-009	Install Fire Extinguisher	BTRUCK	Q	DON	35.13
02-Apr-2021	1	163,898	0	498295	14-059-006	Install Towing Hitch Assembly	BTRUCK	I	DON	1,349.68
02-Apr-2021	1	163,898	0	498295	24-002-022	Repair Rear Door Mechanism	BTRUCK	I	DON	242.78
02-Apr-2021	1	163,898	0	498295	24-034-004	Repair Clearance & Marker Lamps	BTRUCK	I	DON	130.82
02-Apr-2021	1	163,898	0	498295	38-045	Service Power Plant	BTRUCK	P	DON	96.78
27-Oct-2021	0	163,898	0	542174	24-017-001	Repair Tire - Pneumatic	BVLOFC	I	DON	35.74
21-Dec-2021	0	163,898	0	555638	03-013-021	Replace Break Away Switch	TRK023	B	DON	170.03
01-Mar-2022	0	163,898	0	570769	03-063-003	Replace Transceiver - GPS Tracker	ELEC02	Q	DON	280.63
12-Apr-2022	1	183,773	0	581328	02-002	Clean Cab & Sheet Metal	BSETUP	N	DON	433.87
12-Apr-2022	1	183,773	0	581328	03-002-001	Replace Radiator Grille	BBODY	A	DON	590.29
12-Apr-2022	1	183,773	0	581328	03-002-004	Replace Hood	BBODY	A	DON	1,145.00
12-Apr-2022	1	183,773	0	581328	03-016-006	Replace Shock Absorber - Rear	BTRUCK	I	DON	243.06
12-Apr-2022	1	183,773	0	581328	03-016-020	Replace Ball Joint - Upper Control Arm	BTRUCK	I	DON	165.85
12-Apr-2022	1	183,773	0	581328	03-016-021	Replace Ball Joint - Lower Control Arm	BTRUCK	I	DON	1,018.35
12-Apr-2022	1	183,773	0	581328	03-018-011	Replace Seal - Wheel	BTRUCK	I	DON	201.75
12-Apr-2022	1	183,773	0	581328	24-013-001	Repair Front Brakes & Drums	BTRUCK	I	DON	400.92

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B2658 - 2014 F150 CREWCAB										
12-Apr-2022 1	183,773	0	581328	24-013-002	Repair Rear Brakes & Drums	18-May-2022 07:03:52	BTRUCK	I	DON	405.62
12-Apr-2022 1	183,773	0	581328	06-100-DOT	Inspect DOT Federal Inspection	02-Jun-2022 15:43:46	BTRUCK	P	DON	149.02
12-Apr-2022 1	183,773	0	581328	06-100-009	Inspect Safety Check	02-Jun-2022 11:02:36	BTRUCK	I	DON	209.04
12-Apr-2022 1	183,773	0	581328	24-002-002	Repair Fenders	03-May-2022 06:21:41	BBODY	A	DON	678.22
12-Apr-2022 1	183,773	0	581328	12-002	Refinish Cab & Sheet Metal	03-May-2022 06:21:45	BBODY	A	DON	499.32
12-Apr-2022 1	183,773	0	581328	03-519-001	Replace Front Bumper	03-May-2022 06:21:32	BBODY	A	DON	1,247.00
12-Apr-2022 1	183,773	0	581328	03-034-001	Replace Headlamps / Fog Lamps	03-May-2022 06:21:38	BBODY	A	DON	313.99
12-Apr-2022 1	183,773	0	581328	03-059-006	Replace Towing Hitch Assembly	17-May-2022 10:54:18	BTRUCK	I	DON	542.23
12-Apr-2022 1	183,773	0	581328	03-022-008	Replace Pinion Seal	09-May-2022 14:01:41	BTRUCK	I	DON	93.97
12-Apr-2022 1	183,773	0	581328	03-032-001	Replace Battery	09-May-2022 10:38:42	BTRUCK	I	DON	134.19
12-Apr-2022 1	183,773	0	581328	03-032-002	Replace Starter	09-May-2022 15:34:09	BTRUCK	I	DON	326.49
12-Apr-2022 1	183,773	0	581328	14-051-009	Install Fire Extinguisher	09-May-2022 10:48:20	BTRUCK	Q	DON	43.21
12-Apr-2022 1	183,773	0	581328	32-017-001	Balance Tire - Pneumatic	07-Jun-2022 08:46:31	BTRUCK	I	DON	82.62
12-Apr-2022 1	183,773	0	581328	06-100-PMB	Inspect B PMI	06-Jun-2022 14:30:20	BTRUCK	P	DON	49.53
12-Apr-2022 1	183,773	0	581328	09-010-001	Align All Axles	07-Jun-2022 08:46:25	BTRUCK	I	DON	114.14
12-Apr-2022 1	183,773	0	581328	24-017-001	Repair Tire - Pneumatic	02-Jun-2022 15:45:29	BTRUCK	I	DON	95.29
24-Jun-2022 1	184,065	8	598567	24-052-003	Repair Radio Equipment	29-Jun-2022 15:50:40	BTRUCK	I	DON	499.20
24-Jun-2022 1	184,065	8	598567	03-015-002	Replace Steering Shaft Support	27-Jun-2022 17:03:28	BTRUCK	I	DON	330.05
24-Jun-2022 1	184,065	8	598567	24-042-012	Repair Clamps and Hoses	29-Jun-2022 07:22:13	BTRUCK	I	DON	36.47
24-Jun-2022 1	184,065	8	598567	24-049-001	Repair ECM Fault Code	08-Jul-2022 16:16:04	BTRUCK	O	DON	205.00
13-Oct-2022 0	187,708		623815	14-519-003	Install Hitch Assembly	10-Nov-2022 10:38:45	PERSHP	N	DON	4.16
18-Jan-2023 0	190,466		645948	03-013-037	Replace Caliper - Front	19-Jan-2023 07:50:15	PERSHP	I	DON	310.15
18-Jan-2023 0	190,466		645948	06-100-PMMA	Inspect A PMI	18-Jan-2023 10:17:42	PERSHP	P	DON	67.86
18-Jan-2023 0	190,466		645948	38-100-PMMA	Service A PMI	24-Jan-2023 11:36:46	PERSHP	P	DON	95.90
31-Jan-2023 0	190,947		649307	03-001-025	Replace Resistor - Blower Motor	31-Jan-2023 08:00:00	BVLOFC	B	DON	669.85
09-Jun-2023 1	194,948		680238	03-034-002	Replace Stop, Tail, Turn & License	09-Jun-2023 12:24:24	PERSHP	I	DON	14.04
15-Sep-2023 1	199,289		705598	03-002-028	Replace Adjuster - Front Seat	24-Oct-2023 14:49:04	PERSHP	I	DON	1,372.80
22-Nov-2023 1	199,317		722319	06-100-009	Inspect Safety Check	28-Nov-2023 10:57:48	BTRUCK	I	DON	44.00
22-Nov-2023 1	199,317		722319	25-513-004	Remove Specialty Attachment	28-Nov-2023 16:06:41	BTRUCK	I	DON	174.66

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B2658 - 2014 F150 CREWCAB										
01-Dec-2023	1	199,317	724146	02-002	Clean Cab & Sheet Metal	06-Dec-2023 07:52:09	BSETUP	Z	DON	375.62
01-Dec-2023	1	199,317	724146	25-051	Remove General Accessories	04-Dec-2023 07:06:25	BSETUP	Z	DON	132.88

Unit No: B2658 Count: 147 **34,900.55**