

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: E0649 - 2005 JLG 660SJ										
24-Aug-2009	1,078		19989	06-100-001	Inspect DO NOT USE - PMI Service	31-Aug-2009 15:00:00	MPNSHP	P	DON	74.96
24-Aug-2009	1,078		19989	24-053-008	Repair Hoses & Tubings & Fittings	31-Aug-2009 11:17:54	MPNSHP	I	DON	8.62
24-Aug-2009	1,078		19989	24-268-003	Repair Hydraulics	01-Sep-2009 11:52:57	MPNSHP	I	DON	125.43
23-Nov-2009	1,078		27204	06-100-009	Inspect Safety Check	23-Nov-2009 14:49:52	MPNSHP	P	DON	93.90
14-Dec-2009	1,147		30307	03-045	Replace Power Plant	31-Dec-2009 12:45:51	MPNSHP	B	DON	58.67
28-Jan-2010	1,147		32864	06-100-001	Inspect DO NOT USE - PMI Service	28-Jan-2010 15:00:00	MPNSHP	I	DON	145.01
28-Jan-2010	1,147		32864	06-100-009	Inspect Safety Check	28-Jan-2010 15:20:24	MPNSHP	P	DON	51.34
28-Jan-2010	1,147		32864	06-100-011	Inspect Annual Aerial/Boom Inspection	09-Feb-2010 15:47:10	MPNSHP	P	DON	325.37
16-Mar-2010	1,147		36259	06-100-009	Inspect Safety Check	16-Mar-2010 09:00:00	MPNSHP	P	DON	79.16
29-Mar-2010	1,147		37243	24-268-014	Repair Leveling Assembly	05-Apr-2010 10:12:31	MPNSHP	I	DON	222.34
07-Apr-2010	1,147		37849	06-100-009	Inspect Safety Check	07-Apr-2010 09:00:00	MPNSHP	P	DON	128.67
24-Aug-2010	1,663		48514	02-002-044	Clean Cab - Complete	30-Aug-2010 07:02:05	MPNSHP	P	DON	41.90
24-Aug-2010	1,663		48514	03-045-026	Replace Tensioner - Engine Belts	27-Aug-2010 15:38:35	MPNSHP	I	DON	156.47
24-Aug-2010	1,663		48514	03-053-005	Replace Markings - Vehicle - Decals	27-Aug-2010 15:56:53	MPNSHP	I	DON	17.03
24-Aug-2010	1,663		48514	03-065-007	Replace Hoses & Fittings	27-Aug-2010 15:00:00	MPNSHP	I	DON	360.26
24-Aug-2010	1,663		48514	06-100-001	Inspect DO NOT USE - PMI Service	30-Aug-2010 07:31:13	MPNSHP	O	DON	187.61
24-Aug-2010	1,663		48514	24-527	Repair Basket	27-Aug-2010 16:31:01	MPNSHP	I	DON	20.51
11-Oct-2010	1,751		53234	35-065-001	Diagnose Hydraulic Systems	05-Nov-2010 10:42:08	MPNSHP	B	DON	438.28
16-Dec-2010	1,892		55561	01-065-007	Adjust Hoses & Fittings	17-Dec-2010 09:00:00	MPNSHP	I	DON	59.79
16-Dec-2010	1,892		55561	03-052-011	Replace Auxiliary Power		MPNSHP	B	CAN	0.00
16-Dec-2010	1,892		55561	03-053-005	Replace Markings - Vehicle - Decals	21-Dec-2010 08:02:38	MPNSHP	I	DON	59.49
16-Dec-2010	1,892		55561	06-100-009	Inspect Safety Check	17-Dec-2010 14:12:00	MPNSHP	P	DON	119.06
16-Dec-2010	1,892		55561	06-100-011	Inspect Annual Aerial/Boom Inspection	29-Dec-2010 09:22:33	MPNSHP	P	DON	306.60
16-Dec-2010	1,892		55561	24-065-004	Repair Cylinder		MPNSHP	I	CAN	0.00
16-Dec-2010	1,892		55561	26-268-008	Weld Personnel Bucket	17-Dec-2010 13:51:36	MPNSHP	I	DON	38.20
16-Dec-2010	1,892		55561	38-100-001	Service DO NOT USE - PMI Service	26-Jan-2011 14:25:08	MPNSHP	I	DON	145.61
26-Mar-2011	0		62002	06-268-009	Inspect Boom Structure	26-Mar-2011 10:09:18	MPNSHP	P	DON	46.44
26-Jan-2012	1,892		80663	06-100-301	Inspect Annual Service	29-Feb-2012 06:25:13	BSMEQP	I	DON	2,331.47
26-Jan-2012	1,892		80663	24-267-005	Repair Controls	29-Feb-2012 06:25:21	MPNSHP	E	DON	0.00

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: E0649 - 2005 JLG 660SJ										
22-Aug-2012 1	1,892		94801	24-017-001	Repair Tire - Pneumatic		BTIRE	F	CAN	0.00
22-Oct-2012 1	1,892		99128	38-100-001	Service DO NOT USE - PMI Service	23-Oct-2012 15:29:22	BSMEQP	J	DON	277.28
18-Mar-2013 0	2,133		111288	06-100-011	Inspect Annual Aerial/Boom Inspection	27-Jun-2013 10:50:13	BSMEQP	J	DON	2,222.95
28-Oct-2013 1	2,203		135124	06-100	Inspect PMI	06-Nov-2013 14:45:14	BSMEQP	J	DON	360.34
28-Oct-2013 1	2,203		135124	24-063	Repair Satellite Communications System	29-Oct-2013 08:03:44	MPNSHP	J	DON	352.01
13-Mar-2014 0	2,268		149943	06-100-011	Inspect Annual Aerial/Boom Inspection	26-Jun-2014 06:02:31	BSMEQP	J	DON	8,942.14
18-Aug-2015 0	2,385		211625	24-065	Repair Hydraulic Systems - Special Application:	30-Sep-2015 13:53:28	BSMEQP	B	DON	623.66
04-Apr-2016 1	2,385		239938	06-045	Inspect Power Plant	05-Apr-2016 12:00:00	BSMEQP	O	DON	80.42
04-Apr-2016 1	2,385		239938	06-100-PMA	Inspect A PMI	04-Apr-2016 15:24:03	MPNSHP	P	DON	136.78
26-Jul-2017 08	2,645		298280	24-021	Repair Axles - Driven, Front Steering	26-Jul-2017 08:56:12	BVLOFC	O	DON	314.04
21-Mar-2018 0	2,645		328065	02-266	Clean Forklift	21-Mar-2018 13:24:23	BWASH	J	DON	64.30
23-Mar-2018 0	2,810		328458	03-071-005	Replace Side Door Assembly - Hinged	10-Apr-2018 07:21:41	BSMEQP	I	DON	237.80
23-Mar-2018 0	2,810		328458	03-121	Replace Final Drive	10-Apr-2018 15:59:22	BSMEQP	I	DON	3,118.99
23-Mar-2018 0	2,810		328458	06-100-PMA	Inspect A PMI	18-Apr-2018 14:33:55	BSMEQP	P	DON	225.15
23-Mar-2018 0	2,810		328458	24-017-011	Repair Tire - Foam Filled	10-Apr-2018 16:00:57	BSMEQP	I	DON	2,255.79
23-Mar-2018 0	2,810		328458	24-030	Repair Electrical Group	18-Apr-2018 14:32:52	BSMEQP	I	DON	816.05
23-Mar-2018 0	2,810		328458	24-065-004	Repair Cylinder	10-Apr-2018 10:45:39	BSMEQP	I	DON	1,549.90
23-Mar-2018 0	2,810		328458	35-065-004	Diagnose Cylinder	10-Apr-2018 10:41:46	BSMEQP	I	DON	578.03
23-Mar-2018 0	2,810		328458	35-065-005	Diagnose Drive - Motor / Pump	09-Apr-2018 12:00:05	BSMEQP	I	DON	567.95
23-Mar-2018 0	2,810		328458	38-100-301	Service Annual Service	18-Apr-2018 14:33:51	BSMEQP	P	DON	642.53
01-Oct-2019 1	3,040		405425	03-032-001	Replace Battery	03-Oct-2019 07:48:44	BSMEQP	B	DON	0.00
01-Oct-2019 1	3,040		405425	03-063-003	Replace Transceiver - GPS Tracker	02-Oct-2019 08:29:56	BSMEQP	I	DON	356.73
01-Oct-2019 1	3,040		405425	06-100-PMC	Inspect C PMI	03-Oct-2019 10:57:45	BSMEQP	P	DON	260.80
01-Oct-2019 1	3,040		405425	38-040	Service Engine / Motor Systems Group	03-Oct-2019 08:52:15	BSMEQP	P	DON	194.03
30-Oct-2019 0	3,086		410227	03-017-011	Replace Tire - Foam Filled	13-Dec-2019 09:32:25	BSMEQP	I	DON	4,632.42
30-Oct-2019 0	3,086		410227	03-030	Replace Electrical Group	13-Dec-2019 09:32:37	BSMEQP	I	DON	5,399.33
30-Oct-2019 0	3,086		410227	03-032-001	Replace Battery	30-Oct-2019 10:54:22	BSMEQP	B	DON	136.16
30-Oct-2019 0	3,086		410227	03-053-005	Replace Markings - Vehicle - Decals	13-Dec-2019 09:32:34	BSMEQP	I	DON	0.00
30-Oct-2019 0	3,086		410227	03-527	Replace Basket	13-Dec-2019 09:32:28	BSMEQP	I	DON	0.00

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: E0649 - 2005 JLG 660SJ										
30-Oct-2019 0	3,086		410227	06-100-FRK	Inspect Forklift Inspection	16-Dec-2019 07:55:18	BSMEQP	P	DON	190.05
30-Oct-2019 0	3,086		410227	11-065-004	Rebuild Cylinder	13-Dec-2019 09:32:30	BSMEQP	I	DON	0.00
23-Jun-2020 0	3,129		446943	24-065-004	Repair Cylinder	26-Jun-2020 00:00:00	BVLOFC	O	DON	821.20
23-Jun-2020 0	3,129		446943	95-MSC	Travel Miscellaneous	26-Jun-2020 00:00:00	BVLOFC	O	DON	332.40
24-Feb-2021 1	3,154		490068	06-100-FRK	Inspect Forklift Inspection	29-Jun-2021 06:53:23	BSMEQP	P	DON	0.00
24-Feb-2021 1	3,154		490068	06-100-PMA	Inspect A PMI	29-Jun-2021 06:53:29	BSMEQP	P	DON	0.00
24-Feb-2021 1	3,154		490068	06-100-PMB	Inspect B PMI	29-Jun-2021 06:53:31	BSMEQP	P	DON	0.00
24-Feb-2021 1	3,154		490068	06-100-PMC	Inspect C PMI	29-Jun-2021 06:53:34	BSMEQP	P	DON	0.00
24-Feb-2021 1	3,154		490068	38-100-PMC	Service C PMI	29-Jun-2021 10:01:16	BVLOFC	P	DON	3,428.89
14-Oct-2021 1	3,165		539235	38-065	Service Hydraulic Systems - Special Applicator	14-Oct-2021 12:47:48	BSMEQP	I	DON	81.17
08-Feb-2022 1	3,301		564958	06-100-PMA	Inspect A PMI	08-Feb-2022 16:17:51	OTSSHP	P	DON	97.26
08-Feb-2022 1	3,301		564958	24-002-020	Repair Side Door Mechanism	08-Feb-2022 13:39:37	OTSSHP	N	DON	81.67
08-Feb-2022 1	3,301		564958	24-268-045	Repair Man Bucket	08-Feb-2022 15:18:26	OTSSHP	I	DON	109.15
27-Jul-2022 13	3,486		605436	06-100-011	Inspect Annual Aerial/Boom Inspection	06-Oct-2022 07:22:01	BSMEQP	N	DON	190.66
27-Jul-2022 13	3,486		605436	24-266	Repair Forklift	06-Oct-2022 07:22:04	BSMEQP	I	DON	540.94
27-Jul-2022 13	3,486		605436	38-040	Service Engine / Motor Systems Group	06-Oct-2022 07:21:59	BSMEQP	P	DON	415.53
31-Mar-2023 1	3,561		663486	38-040	Service Engine / Motor Systems Group	31-Mar-2023 14:22:12	BSMEQP	P	DON	197.46
07-Nov-2023 1	3,708		718904	06-100-011	Inspect Annual Aerial/Boom Inspection	05-Dec-2023 06:21:18	BSMEQP	P	DON	213.75
07-Nov-2023 1	3,708		718904	24-266	Repair Forklift	04-Dec-2023 15:04:35	BSMEQP	I	DON	170.30
07-Nov-2023 1	3,708		718904	25-051	Remove General Accessories	08-Dec-2023 16:31:14	BSETUP	Z	DON	159.57
07-Nov-2023 1	3,708		718904	27-266	De-Identify Forklift		BSMEQP	Z	CAN	0.00
07-Nov-2023 1	3,708		718904	38-040	Service Engine / Motor Systems Group	05-Dec-2023 06:21:21	BSMEQP	P	DON	361.50

Unit No: E0649

Count: 80

47,379.27