

# Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
<b>Unit No: B2525 - 2014 F250 CREWCAB</b>										
12-May-2014	63	0	157447	14-034-006	Install Warning Lamps - Special Application	13-May-2014 08:42:20	BDETL	C	DON	417.94
12-May-2014	63	0	157447	14-052-015	Install Power Inverter/Converter	12-Jun-2014 10:41:39	BDETL	C	DON	537.36
12-May-2014	63	0	157447	14-053-005	Install Markings - Vehicle - Decals	13-May-2014 08:45:32	BDETL	C	DON	104.86
12-May-2014	63	0	157447	14-071-011	Install Scuff Liner / Bed Mat	13-May-2014 06:17:24	BDETL	C	DON	80.18
12-May-2014	63	0	157447	14-002-003	Install Running Boards / Step Tubes	13-May-2014 07:56:59	BDETL	C	DON	299.76
12-May-2014	63	0	157447	03-032-001	Replace Battery	17-Jun-2014 12:38:11	BSETUP	I	DON	12.32
12-May-2014	63	0	157447	14-506-001	Install Fuel Tank	13-May-2014 07:56:51	BDETL	C	DON	1,016.49
12-May-2014	63	0	157447	14-510-002	Install Tool Box	13-May-2014 07:55:57	BDETL	C	DON	331.12
12-May-2014	63	0	157447	14-517	Install Safety Equipment	13-May-2014 09:23:00	BDETL	C	DON	93.04
12-May-2014	63	0	157447	14-078-009	Install Mud Flaps and Hanger Brackets	13-May-2014 07:56:55	BDETL	C	DON	22.78
12-May-2014	63	0	157447	14-052-003	Install Radio Equipment	13-May-2014 08:02:08	BDETL	C	DON	1,060.00
12-May-2014	63	0	157447	14-052-014	Install Cellular Telephone Accessories	13-May-2014 08:24:58	BDETL	C	DON	62.09
12-May-2014	63	0	157447	06-100-DOT	Inspect DOT Federal Inspection	13-May-2014 13:19:39	BTRUCK	P	DON	26.50
12-May-2014	63	0	157447	01-042-002	Adjust Radiator	13-May-2014 13:28:06	BTRUCK	I	DON	989.12
12-May-2014	63	0	157447	14-079-002	Install Headache Rack	13-May-2014 07:56:46	BDETL	C	DON	348.84
12-May-2014	63	0	157447	14-079-003	Install Strap, Anti-Static	13-May-2014 07:57:03	BDETL	C	DON	4.59
29-Sep-2014	4,460		173940	14-016-005	Install Chassis Spring - Rear	30-Sep-2014 09:00:02	BTRUCK	C	DON	627.63
29-Sep-2014	4,460		173940	38-045	Service Power Plant	30-Sep-2014 10:30:31	BTRUCK	P	DON	60.98
29-Sep-2014	4,460		173940	06-100-PMB	Inspect B PMI	30-Sep-2014 14:06:29	BTRUCK	P	DON	131.87
29-Sep-2014	4,460		173940	24-034-014	Repair Auxiliary Work / Flood Light	30-Sep-2014 13:33:20	BTRUCK	I	DON	92.97
19-Feb-2015	11,202		192085	06-100-DOT	Inspect DOT Federal Inspection	20-Feb-2015 07:32:02	BTRUCK	P	DON	18.03
19-Feb-2015	11,202		192085	06-100-PMB	Inspect B PMI	20-Feb-2015 06:10:41	BTRUCK	P	DON	7.16
19-Feb-2015	11,202		192085	03-051-009	Replace Fire Extinguisher	20-Feb-2015 07:47:13	BTRUCK	I	DON	56.29
19-Feb-2015	11,202		192085	38-045	Service Power Plant	19-Feb-2015 17:00:03	BTRUCK	P	DON	95.52
19-Feb-2015	11,202		192085	03-002-035	Replace Windshield Wiper & Washer	20-Feb-2015 07:45:32	BTRUCK	I	DON	28.71
19-Feb-2015	11,202		192085	31-017-001	Rotate Tire - Pneumatic	20-Feb-2015 06:59:24	BTRUCK	I	DON	26.92
20-May-2015	16,618		201680	38-045	Service Power Plant	20-May-2015 16:00:35	BTRUCK	P	DON	88.96
20-May-2015	16,618		201680	06-100-DOT	Inspect DOT Federal Inspection		BTRUCK	P	CAN	0.00
20-May-2015	16,618		201680	06-100-PMB	Inspect B PMI	20-May-2015 14:46:41	BTRUCK	P	DON	20.29

# Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
<b>Unit No: B2525 - 2014 F250 CREWCAB</b>										
02-Nov-2016 C	47,419		265294	06-100-DOT	Inspect DOT Federal Inspection	04-Nov-2016 07:38:44	BTRUCK	P	DON	33.27
02-Nov-2016 C	47,419		265294	06-100-PMB	Inspect B PMI	04-Nov-2016 06:38:57	BTRUCK	P	DON	124.10
02-Nov-2016 C	47,419		265294	38-045	Service Power Plant	04-Nov-2016 08:48:42	BTRUCK	P	DON	47.15
02-Nov-2016 C	47,419		265294	14-051-009	Install Fire Extinguisher	04-Nov-2016 09:20:57	BTRUCK	I	DON	141.12
02-Nov-2016 C	47,419		265294	03-002-035	Replace Windshield Wiper & Washer	04-Nov-2016 08:52:51	BTRUCK	I	DON	70.97
02-Nov-2016 C	47,419		265294	31-017-001	Rotate Tire - Pneumatic	04-Nov-2016 08:19:09	BTRUCK	P	DON	22.49
02-Nov-2016 C	47,419		265294	24-002	Repair Cab & Sheet Metal		BBODY	E	CAN	0.00
02-Nov-2016 C	47,419		265294	03-002-015	Replace Quarter & Deck Panels - Rear	15-Nov-2016 12:45:09	BBODY	E	DON	1,496.08
02-Nov-2016 C	47,419		265294	12-002-015	Refinish Quarter & Deck Panels - Rear	11-Nov-2016 15:55:02	BBODY	E	DON	266.24
10-May-2017 (	57,213		288314	06-100-PMB	Inspect B PMI	11-May-2017 08:25:01	BTRUCK	P	DON	63.04
10-May-2017 (	57,213		288314	38-045	Service Power Plant	11-May-2017 08:42:39	BTRUCK	P	DON	40.31
10-May-2017 (	57,213		288314	03-017-001	Replace Tire - Pneumatic	11-May-2017 10:52:53	BTRUCK	O	DON	918.73
10-May-2017 (	57,213		288314	06-100-DOT	Inspect DOT Federal Inspection	11-May-2017 09:21:45	BTRUCK	P	DON	17.07
10-May-2017 (	57,213		288314	14-051-009	Install Fire Extinguisher	11-May-2017 09:42:24	BTRUCK	I	DON	136.23
10-May-2017 (	57,213		288314	03-002-035	Replace Windshield Wiper & Washer	11-May-2017 09:23:24	BTRUCK	I	DON	23.66
19-Sep-2017 (	69,972		306113	24-017-001	Repair Tire - Pneumatic	19-Sep-2017 10:38:00	BTIRE	F	DON	31.89
27-Oct-2017 (	74,939		313828	06-100-PMA	Inspect A PMI	27-Oct-2017 09:24:00	BVLOFC	P	DON	116.88
17-Jan-2018 (	78,090		319852	03-031-001	Replace Generator/Alternator	17-Jan-2018 10:04:32	BVLOFC	B	DON	409.33
22-Feb-2018 (	80,577		324659	03-041-007	Replace Filter - Outer	26-Feb-2018 08:40:37	BVLOFC	P	DON	34.42
22-Feb-2018 (	80,577		324659	06-100-PMA	Inspect A PMI	26-Feb-2018 08:40:35	BVLOFC	P	DON	44.52
22-Feb-2018 (	80,577		324659	38-042	Service Cooling System	26-Feb-2018 08:46:15	BVLOFC	P	DON	131.02
22-Feb-2018 (	80,577		324659	03-013-002	Replace Rear Brakes & Drums	26-Feb-2018 08:40:30	BVLOFC	I	DON	200.99
22-Feb-2018 (	80,577		324659	03-033-004	Replace Spark Plug Wires	26-Feb-2018 08:47:32	BVLOFC	I	DON	215.35
22-Feb-2018 (	80,577		324659	03-034-001	Replace Headlamps / Fog Lamps		BVLOFC	O	CAN	0.00
22-Feb-2018 (	80,577		324659	38-013	Service Brakes	26-Feb-2018 08:46:53	BVLOFC	P	DON	163.21
02-Apr-2018 (	81,713		329596	09-015	Align Steering	09-Apr-2018 10:45:09	BVLOFC	I	DON	0.00
02-Apr-2018 (	81,713		329596	03-016-003	Replace Shock Absorber - Front	09-Apr-2018 10:45:14	BVLOFC	O	DON	259.38
02-Apr-2018 (	81,713		329596	03-041-007	Replace Filter - Outer	09-Apr-2018 10:48:25	BVLOFC	P	DON	46.81
02-Apr-2018 (	81,713		329596	03-002-024	Replace Glass / Windshield	09-Apr-2018 10:44:59	BVLOFC	O	DON	288.77

# Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
<b>Unit No: B2525 - 2014 F250 CREWCAB</b>										
02-Apr-2018	1	81,713	329596	03-013-001	Replace Front Brakes & Drums	09-Apr-2018 10:49:45	BVLOFC	O	DON	446.46
02-Apr-2018	1	81,713	329596	03-015-004	Replace Steering Linkage	09-Apr-2018 10:45:18	BVLOFC	I	DON	1,517.00
02-Apr-2018	1	81,713	329596	24-033-002	Repair Distributor / Coil Pack	09-Apr-2018 10:45:22	BVLOFC	O	DON	430.63
02-Apr-2018	1	81,713	329596	03-045	Replace Power Plant	09-Apr-2018 10:45:04	BVLOFC	I	DON	1,917.39
06-Sep-2018	0	92,237	351042	06-100-PMA	Inspect A PMI	06-Sep-2018 08:48:24	BVLOFC	P	DON	42.43
12-Oct-2018	0	94,868	356298	03-041-007	Replace Filter - Outer	12-Oct-2018 11:50:18	BVLOFC	P	DON	48.02
12-Oct-2018	0	94,868	356298	03-033-002	Replace Distributor / Coil Pack	12-Oct-2018 11:50:18	BVLOFC	I	DON	550.60
05-Nov-2018	0	95,364	359465	03-002-001	Replace Radiator Grille	06-Nov-2018 07:33:41	BTRUCK	O	DON	353.97
05-Nov-2018	0	95,364	359465	03-017-001	Replace Tire - Pneumatic	05-Nov-2018 15:33:14	BTRUCK	O	DON	1,082.20
05-Nov-2018	0	95,364	359465	06-100-DOT	Inspect DOT Federal Inspection	05-Nov-2018 13:06:11	BTRUCK	P	DON	27.91
05-Nov-2018	0	95,364	359465	14-051-009	Install Fire Extinguisher	06-Nov-2018 05:59:13	BTRUCK	I	DON	44.01
05-Nov-2018	0	95,364	359465	03-044-002	Replace Filters	06-Nov-2018 05:55:14	BTRUCK	I	DON	10.06
05-Nov-2018	0	95,364	359465	03-002-035	Replace Windshield Wiper & Washer	06-Nov-2018 05:36:54	BTRUCK	I	DON	41.33
05-Nov-2018	0	95,364	359465	03-016-006	Replace Shock Absorber - Rear	06-Nov-2018 06:56:10	BTRUCK	I	DON	160.63
05-Nov-2018	0	95,364	359465	03-034-003	Replace Signal, Parking, Backup Lamps	05-Nov-2018 16:15:44	BTRUCK	I	DON	142.34
05-Nov-2018	0	95,364	359465	02-002	Clean Cab & Sheet Metal	07-Nov-2018 17:00:32	BSETUP	N	DON	258.70
05-Nov-2018	0	95,364	359465	06-100-PMB	Inspect B PMI	05-Nov-2018 12:15:19	BTRUCK	P	DON	41.08
05-Nov-2018	0	95,364	359465	38-045	Service Power Plant	06-Nov-2018 12:00:06	BTRUCK	P	DON	296.89
31-Dec-2018	0	95,459	366278	02-002	Clean Cab & Sheet Metal	31-Dec-2018 09:38:15	BSETUP	I	DON	15.17
27-Jul-2019	13	116,060	400371	38-100-PMA	Service A PMI	27-Jul-2019 13:21:00	BVLOFC	P	DON	62.39
27-Aug-2019	0	117,036	400470	02-002	Clean Cab & Sheet Metal	05-Sep-2019 16:01:27	BSETUP	I	DON	232.18
27-Aug-2019	0	117,036	400470	03-001-012	Replace Condenser Assembly	29-Aug-2019 12:00:39	BTRUCK	I	DON	275.29
27-Aug-2019	0	117,036	400470	03-002	Replace Cab & Sheet Metal		BTRUCK	I	CAN	0.00
27-Aug-2019	0	117,036	400470	03-002-001	Replace Radiator Grille	03-Sep-2019 14:22:16	BTRUCK	I	DON	460.03
27-Aug-2019	0	117,036	400470	03-002-035	Replace Windshield Wiper & Washer	04-Sep-2019 05:37:25	BTRUCK	I	DON	29.59
27-Aug-2019	0	117,036	400470	03-013-001	Replace Front Brakes & Drums	03-Sep-2019 08:47:14	BTRUCK	I	DON	131.46
27-Aug-2019	0	117,036	400470	03-014-007	Replace License Carrier	04-Sep-2019 05:24:35	BTRUCK	I	DON	24.51
27-Aug-2019	0	117,036	400470	03-015-004	Replace Steering Linkage	03-Sep-2019 10:26:22	BTRUCK	I	DON	477.50
27-Aug-2019	0	117,036	400470	03-018-001	Replace Front Axle Hubs & Bearings	29-Aug-2019 15:14:10	BTRUCK	I	DON	1,378.93

# Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B2525 - 2014 F250 CREWCAB										
27-Aug-2019 C	117,036		400470	03-018-011	Replace Seal - Wheel	03-Sep-2019 10:00:44	BTRUCK	I	DON	40.33
27-Aug-2019 C	117,036		400470	03-024-005	Replace Universal Joint	03-Sep-2019 07:31:11	BTRUCK	I	DON	89.98
27-Aug-2019 C	117,036		400470	03-044-018	Replace Fuel Hose / Line	03-Sep-2019 16:03:22	BTRUCK	I	DON	32.44
27-Aug-2019 C	117,036		400470	03-051-009	Replace Fire Extinguisher	04-Sep-2019 05:18:45	BTRUCK	I	DON	162.33
27-Aug-2019 C	117,036		400470	03-053-005	Replace Markings - Vehicle - Decals	09-Sep-2019 09:56:56	BSETUP	I	DON	46.53
27-Aug-2019 C	117,036		400470	03-079-003	Replace Strap, Anti-Static	09-Sep-2019 10:41:47	BSETUP	I	DON	21.83
27-Aug-2019 C	117,036		400470	06-100-DOT	Inspect DOT Federal Inspection	03-Sep-2019 15:48:36	BTRUCK	P	DON	47.37
27-Aug-2019 C	117,036		400470	06-100-PMB	Inspect B PMI	27-Aug-2019 16:00:31	BTRUCK	P	DON	16.81
27-Aug-2019 C	117,036		400470	24-016-001	Repair Independent Front Suspension	27-Aug-2019 15:29:53	BTRUCK	O	DON	103.20
27-Aug-2019 C	117,036		400470	24-045	Repair Power Plant	03-Sep-2019 10:54:03	BTRUCK	I	DON	130.25
27-Aug-2019 C	117,036		400470	38-045	Service Power Plant	03-Sep-2019 12:00:17	BTRUCK	P	DON	65.13
27-Aug-2019 C	117,036		400470	03-510-002	Replace Tool Box	05-Sep-2019 17:00:17	BSETUP	I	DON	19.06
21-Nov-2019 I	124,794		413854	03-044-003	Replace Fuel Pump	03-Dec-2019 11:56:01	BSETUP	I	DON	45.98
21-Nov-2019 I	124,794		413854	03-506-001	Replace Fuel Tank	03-Dec-2019 11:01:22	BSETUP	I	DON	117.78
21-Nov-2019 I	124,794		413854	06-100-PMB	Inspect B PMI	22-Nov-2019 09:34:12	BTRUCK	P	DON	60.98
21-Nov-2019 I	124,794		413854	02-002	Clean Cab & Sheet Metal	02-Dec-2019 13:24:06	BSETUP	I	DON	207.52
21-Nov-2019 I	124,794		413854	24-032	Repair Cranking System	25-Nov-2019 10:57:14	BTRUCK	O	DON	216.21
21-Nov-2019 I	124,794		413854	03-033-002	Replace Distributor / Coil Pack	25-Nov-2019 08:27:14	BTRUCK	I	DON	527.61
21-Nov-2019 I	124,794		413854	03-053-005	Replace Markings - Vehicle - Decals	03-Dec-2019 11:01:39	BSETUP	I	DON	31.19
21-Nov-2019 I	124,794		413854	38-045	Service Power Plant	22-Nov-2019 10:43:21	BTRUCK	P	DON	51.41
21-Nov-2019 I	124,794		413854	24-002-024	Repair Glass / Windshield	25-Nov-2019 06:47:47	BTRUCK	I	DON	51.13
21-Nov-2019 I	124,794		413854	24-034-003	Repair Signal, Parking, Backup Lamps	22-Nov-2019 10:10:04	BTRUCK	O	DON	19.68
21-Nov-2019 I	124,794		413854	24-045-021	Repair Electronic Engine Controls	25-Nov-2019 12:00:42	BTRUCK	O	DON	47.52
21-Nov-2019 I	124,794		413854	14-053-004	Install Safety Equipment	03-Dec-2019 11:01:30	BSETUP	I	DON	45.72
07-May-2020 C	132,559		439711	03-063-003	Replace Transceiver - GPS Tracker	07-May-2020 08:52:53	ELEC02	Q	DON	195.23
08-Jun-2020 I	134,790		444213	06-100-PMB	Inspect B PMI	10-Jun-2020 06:51:47	BTRUCK	P	DON	19.73
08-Jun-2020 I	134,790		444213	03-017-001	Replace Tire - Pneumatic	11-Jun-2020 07:45:09	BTRUCK	O	DON	1,002.59
08-Jun-2020 I	134,790		444213	24-045-023	Repair Engine Belts	09-Jun-2020 13:40:56	BTRUCK	O	DON	236.06
08-Jun-2020 I	134,790		444213	38-045	Service Power Plant	09-Jun-2020 13:57:17	BTRUCK	P	DON	37.96

# Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
<b>Unit No: B2525 - 2014 F250 CREWCAB</b>										
08-Jun-2020 11	134,790		444213	03-002-035	Replace Windshield Wiper & Washer	09-Jun-2020 14:15:18	BTRUCK	I	DON	28.39
08-Jun-2020 11	134,790		444213	03-002-037	Replace Seat Assembly	10-Jun-2020 06:40:31	BTRUCK	I	DON	310.41
08-Jun-2020 11	134,790		444213	03-034-020	Replace Dome / Reading Light	09-Jun-2020 11:44:03	BTRUCK	I	DON	19.22
08-Jun-2020 11	134,790		444213	03-044-002	Replace Filters	09-Jun-2020 12:00:05	BTRUCK	I	DON	12.37
08-Jun-2020 11	134,790		444213	06-100-DOT	Inspect DOT Federal Inspection	12-Jun-2020 07:05:22	BTRUCK	P	DON	37.65
08-Jun-2020 11	134,790		444213	14-051-006	Install Safety Devices	09-Jun-2020 12:38:01	BTRUCK	I	DON	40.95
08-Jun-2020 11	134,790		444213	14-051-009	Install Fire Extinguisher	09-Jun-2020 12:37:38	BTRUCK	I	DON	151.72
08-Jun-2020 11	134,790		444213	03-043-002	Replace Exhaust Manifold	11-Jun-2020 14:03:39	BTRUCK	I	DON	607.37
22-Jul-2020 10	137,335		451925	03-044-002	Replace Filters	30-Jul-2020 06:36:08	BTRUCK	I	DON	24.02
22-Jul-2020 10	137,335		451925	03-002-035	Replace Windshield Wiper & Washer	29-Jul-2020 16:53:23	BTRUCK	I	DON	24.76
22-Jul-2020 10	137,335		451925	03-034-002	Replace Stop, Tail, Turn & License	29-Jul-2020 17:00:32	BTRUCK	I	DON	5.10
22-Jul-2020 10	137,335		451925	38-045	Service Power Plant	29-Jul-2020 16:41:02	BTRUCK	P	DON	49.27
22-Jul-2020 10	137,335		451925	06-100-PMB	Inspect B PMI	29-Jul-2020 16:12:28	BTRUCK	P	DON	35.45
22-Jul-2020 10	137,335		451925	06-100-009	Inspect Safety Check	29-Jul-2020 15:22:43	BTRUCK	P	DON	45.89
22-Jul-2020 10	137,335		451925	03-002	Replace Cab & Sheet Metal	30-Jul-2020 09:42:34	BBODY	A	DON	2,683.13
22-Jul-2020 10	137,335		451925	12-002	Refinish Cab & Sheet Metal	30-Jul-2020 09:42:38	BBODY	A	DON	326.72
30-Jul-2020 12	137,338		453519	02-002	Clean Cab & Sheet Metal	31-Jul-2020 07:48:05	BSETUP	N	DON	102.11
05-Nov-2020 1	142,546		470552	03-002-067	Replace Keys - Door / Ignition	05-Nov-2020 12:58:55	BVLOFC	O	DON	176.20
05-Nov-2020 1	142,546		470552	38-100-PMA	Service A PMI	05-Nov-2020 12:58:55	BVLOFC	P	DON	101.39
05-Nov-2020 1	142,546		470552	06-100-PMA	Inspect A PMI	05-Nov-2020 12:58:55	BTRUCK	P	DON	0.00
20-Jan-2021 01	144,652		483308	02-002	Clean Cab & Sheet Metal	12-Feb-2021 08:13:39	BSETUP	I	DON	444.01
20-Jan-2021 01	144,652		483308	03-002-035	Replace Windshield Wiper & Washer	28-Jan-2021 16:55:46	BTRUCK	I	DON	50.64
20-Jan-2021 01	144,652		483308	03-021-109	Replace Universal Joint	03-Feb-2021 09:37:04	BTRUCK	I	DON	222.34
20-Jan-2021 01	144,652		483308	03-025-003	Replace Seal - Output Shaft	01-Feb-2021 08:04:09	BTRUCK	I	DON	69.60
20-Jan-2021 01	144,652		483308	03-044-002	Replace Filters	29-Jan-2021 07:19:41	BTRUCK	I	DON	56.82
20-Jan-2021 01	144,652		483308	03-045-026	Replace Tensioner - Engine Belts	29-Jan-2021 08:43:24	BTRUCK	I	DON	197.53
20-Jan-2021 01	144,652		483308	06-100-009	Inspect Safety Check	28-Jan-2021 14:11:26	BTRUCK	P	DON	88.79
20-Jan-2021 01	144,652		483308	06-100-DOT	Inspect DOT Federal Inspection	28-Jan-2021 16:21:02	BTRUCK	P	DON	129.98
20-Jan-2021 01	144,652		483308	06-100-PMB	Inspect B PMI	28-Jan-2021 15:20:47	BTRUCK	P	DON	68.48

# Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
<b>Unit No: B2525 - 2014 F250 CREWCAB</b>										
20-Jan-2021 0:	144,652		483308	14-051-009	Install Fire Extinguisher	28-Jan-2021 17:06:40	BTRUCK	Q	DON	154.49
20-Jan-2021 0:	144,652		483308	24-002-010	Repair Mirrors	02-Feb-2021 15:20:28	BTRUCK	I	DON	102.69
20-Jan-2021 0:	144,652		483308	24-002-030	Repair Interior Moldings	05-Feb-2021 10:17:57	BTRUCK	I	DON	122.24
20-Jan-2021 0:	144,652		483308	24-044-016	Repair Tank - Fuel Auxiliary	01-Feb-2021 07:31:59	BTRUCK	I	DON	152.91
20-Jan-2021 0:	144,652		483308	31-017-001	Rotate Tire - Pneumatic	01-Feb-2021 06:54:59	BTRUCK	P	DON	46.99
20-Jan-2021 0:	144,652		483308	38-045	Service Power Plant	28-Jan-2021 16:21:38	BTRUCK	P	DON	89.33
20-Jan-2021 0:	144,652		483308	03-032-001	Replace Battery	23-Jan-2021 07:32:24	BTRUCK	I	DON	115.32
10-May-2021 1	147,818		505735	24-021	Repair Axles - Driven, Front Steering	12-May-2021 12:58:23	BTRUCK	O	DON	40.39
10-May-2021 1	147,818		505735	38-100-PMA	Service A PMI	11-May-2021 13:54:31	BTRUCK	P	DON	57.86
10-May-2021 1	147,818		505735	06-100-PMB	Inspect B PMI	11-May-2021 13:39:13	BTRUCK	P	DON	62.29
10-May-2021 1	147,818		505735	03-002-035	Replace Windshield Wiper & Washer	11-May-2021 14:15:52	BTRUCK	I	DON	27.87
10-May-2021 1	147,818		505735	24-044-016	Repair Tank - Fuel Auxiliary	11-May-2021 14:38:06	BTRUCK	I	DON	22.83
10-May-2021 1	147,818		505735	31-017-001	Rotate Tire - Pneumatic	11-May-2021 16:00:36	BTRUCK	I	DON	81.56
10-May-2021 1	147,818		505735	03-002-024	Replace Glass / Windshield	12-May-2021 15:17:38	BTRUCK	I	DON	287.33
14-Sep-2021 1	158,032		531152	03-002-035	Replace Windshield Wiper & Washer	15-Sep-2021 10:59:43	BTRUCK	I	DON	16.40
14-Sep-2021 1	158,032		531152	03-013-001	Replace Front Brakes & Drums	15-Sep-2021 12:30:14	BTRUCK	I	DON	404.64
14-Sep-2021 1	158,032		531152	03-013-002	Replace Rear Brakes & Drums	15-Sep-2021 17:01:01	BTRUCK	I	DON	147.93
14-Sep-2021 1	158,032		531152	03-017-001	Replace Tire - Pneumatic	15-Sep-2021 16:42:26	BTRUCK	I	DON	1,150.11
14-Sep-2021 1	158,032		531152	03-018-001	Replace Front Axle Hubs & Bearings	15-Sep-2021 11:14:38	BTRUCK	I	DON	275.25
14-Sep-2021 1	158,032		531152	06-100-PMA	Inspect A PMI	15-Sep-2021 10:20:13	BTRUCK	P	DON	28.14
14-Sep-2021 1	158,032		531152	14-051-006	Install Safety Devices	15-Sep-2021 11:01:58	BTRUCK	I	DON	22.68
14-Sep-2021 1	158,032		531152	24-014-004	Repair Cab & Body Mountings	15-Sep-2021 15:36:20	BTRUCK	O	DON	118.90
14-Sep-2021 1	158,032		531152	24-016-024	Repair Leaf Spring	15-Sep-2021 15:00:35	BTRUCK	I	DON	675.09
14-Sep-2021 1	158,032		531152	38-100-PMA	Service A PMI	15-Sep-2021 10:55:46	BTRUCK	P	DON	95.07
10-Nov-2021 1	162,970		545663	06-100-DOT	Inspect DOT Federal Inspection	10-Nov-2021 13:49:26	BVLOFC	P	DON	0.00
10-Nov-2021 1	162,970		545663	38-100-DOT	Service DOT Federal Inspection	10-Nov-2021 13:49:26	BVLOFC	P	DON	111.40
05-Apr-2022 1	166,406		579700	31-017-001	Rotate Tire - Pneumatic	05-Apr-2022 11:58:48	BVLOFC	P	DON	27.85
05-Apr-2022 1	166,406		579700	35-002-004	Diagnose Hood	05-Apr-2022 11:58:48	BVLOFC	O	DON	0.00
05-Apr-2022 1	166,406		579700	03-041-007	Replace Filter - Outer	05-Apr-2022 11:58:48	BVLOFC	P	DON	66.23

# Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
<b>Unit No: B2525 - 2014 F250 CREWCAB</b>										
05-Apr-2022 1	166,406		579700	38-100-PMA	Service A PMI	05-Apr-2022 11:58:48	BVLOFC	P	DON	106.56
05-Apr-2022 1	166,406		579700	06-100-PMA	Inspect A PMI	05-Apr-2022 11:58:48	BVLOFC	P	DON	0.00
02-Jun-2022 1:	171,045		593054	03-033	Replace Ignition System	02-Jun-2022 12:51:17	BVLOFC	O	DON	2,444.32
18-Aug-2022 C	178,196		610418	06-100-PMB	Inspect B PMI		BTRUCK	P	CAN	0.00
18-Aug-2022 C	178,196		610418	38-100-PMA	Service A PMI		BTRUCK	P	CAN	0.00
18-Aug-2022 C	178,196		610418	06-100-DOT	Inspect DOT Federal Inspection		BTRUCK	P	CAN	0.00
22-Sep-2022 0	178,218		618405	03-015-012	Replace Steering Stability System	22-Sep-2022 11:20:06	BTRUCK	I	DON	134.41
22-Sep-2022 0	178,218		618405	24-013-034	Repair Parking Brake - Complete	22-Sep-2022 11:20:03	BTRUCK	I	DON	774.74
22-Sep-2022 0	178,218		618405	24-021-001	Repair Axle Assembly - Driven, Front Steering	22-Sep-2022 11:20:12	BTRUCK	I	DON	43.58
22-Sep-2022 0	178,218		618405	06-100-DOT	Inspect DOT Federal Inspection	22-Sep-2022 11:19:57	BTRUCK	P	DON	186.03
22-Sep-2022 0	178,218		618405	31-017-001	Rotate Tire - Pneumatic	22-Sep-2022 11:20:00	BTRUCK	I	DON	21.21
22-Sep-2022 0	178,218		618405	03-018-012	Replace Cap - Hub	22-Sep-2022 11:20:22	BTRUCK	I	DON	93.17
22-Sep-2022 0	178,218		618405	03-022-008	Replace Pinion Seal	22-Sep-2022 11:20:19	BTRUCK	I	DON	337.13
22-Sep-2022 0	178,218		618405	06-100-PMB	Inspect B PMI	27-Sep-2022 16:26:32	BTRUCK	P	DON	74.06
22-Sep-2022 0	178,218		618405	38-100-PMA	Service A PMI	22-Sep-2022 11:19:53	BTRUCK	P	DON	158.42
22-Sep-2022 0	178,218		618405	14-051-009	Install Fire Extinguisher	27-Sep-2022 17:00:04	BTRUCK	Q	DON	178.80
22-Sep-2022 0	178,218		618405	24-034-006	Repair Warning Lamps - Special Application	28-Sep-2022 06:32:35	BTRUCK	I	DON	41.71
22-Sep-2022 0	178,218		618405	24-002-072	Repair Rear Window	28-Sep-2022 14:31:33	BTRUCK	I	DON	108.95
22-Sep-2022 0	178,218		618405	03-079-003	Replace Strap, Anti-Static	28-Sep-2022 06:48:23	BTRUCK	I	DON	18.25
22-Sep-2022 0	178,218		618405	02-002	Clean Cab & Sheet Metal	29-Sep-2022 17:01:05	BSETUP	N	DON	466.97
22-Sep-2022 0	178,218		618405	03-051-006	Replace Safety Devices	29-Sep-2022 16:32:05	BSETUP	Q	DON	136.91
22-Sep-2022 0	178,218		618405	03-052-014	Replace Cellular Telephone Accessories	07-Oct-2022 06:58:23	BSETUP	I	DON	27.41
22-Sep-2022 0	178,218		618405	03-016-006	Replace Shock Absorber - Rear	22-Sep-2022 11:20:16	BTRUCK	I	DON	277.86
22-Sep-2022 0	178,218		618405	03-017-001	Replace Tire - Pneumatic	01-Oct-2022 09:23:26	BTIRE	I	DON	10.75
06-Feb-2023 1	185,254		662912	38-100-PMA	Service A PMI	06-Feb-2023 13:39:00	BVLOFC	P	DON	71.30
06-Feb-2023 1	185,254		662912	06-100-PMA	Inspect A PMI	06-Feb-2023 13:38:00	BVLOFC	P	DON	0.00
09-Oct-2023 1:	193,152		711290	06-017-001	Inspect Tire - Pneumatic	10-Oct-2023 09:15:24	BTRUCK	O	DON	23.65
09-Oct-2023 1:	193,152		711290	24-049-001	Repair ECM Fault Code	16-Oct-2023 07:43:08	BTRUCK	O	DON	138.49
09-Oct-2023 1:	193,152		711290	06-100-DOT	Inspect DOT Federal Inspection	10-Oct-2023 16:00:32	BTRUCK	P	DON	39.20

# Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
<b>Unit No: B2525 - 2014 F250 CREWCAB</b>										
09-Oct-2023 1:	193,152		711290	06-100-PMB	Inspect B PMI	10-Oct-2023 08:01:39	BTRUCK	P	DON	41.18
09-Oct-2023 1:	193,152		711290	38-100-PMA	Service A PMI	10-Oct-2023 09:53:26	BTRUCK	P	DON	85.20
09-Oct-2023 1:	193,152		711290	03-032-001	Replace Battery	10-Oct-2023 10:23:27	BTRUCK	I	DON	123.76
09-Oct-2023 1:	193,152		711290	14-051-009	Install Fire Extinguisher	10-Oct-2023 10:30:05	BTRUCK	Q	DON	161.13
09-Oct-2023 1:	193,152		711290	03-002-035	Replace Windshield Wiper & Washer	10-Oct-2023 10:00:16	BTRUCK	I	DON	21.94
09-Oct-2023 1:	193,152		711290	24-079-002	Repair Headache Rack	10-Oct-2023 13:29:22	BTRUCK	I	DON	15.37
09-Oct-2023 1:	193,152		711290	03-018-001	Replace Front Axle Hubs & Bearings	10-Oct-2023 13:06:44	BTRUCK	I	DON	660.57
09-Oct-2023 1:	193,152		711290	01-013-028	Adjust Shoe - Parking Brake	10-Oct-2023 14:18:34	BTRUCK	I	DON	45.76
09-Oct-2023 1:	193,152		711290	01-015-001	Adjust Steering Wheel	11-Oct-2023 06:31:55	BTRUCK	I	DON	58.65
09-Oct-2023 1:	193,152		711290	24-043-003	Repair Muffler	10-Oct-2023 15:22:07	BTRUCK	I	DON	55.63
09-Oct-2023 1:	193,152		711290	02-002	Clean Cab & Sheet Metal	13-Oct-2023 10:44:40	BSETUP	N	DON	383.86
09-Oct-2023 1:	193,152		711290	12-002-003	Refinish Running Boards / Step Tubes	13-Oct-2023 08:36:21	BSETUP	I	DON	148.91
09-Oct-2023 1:	193,152		711290	03-051-006	Replace Safety Devices	13-Oct-2023 10:43:21	BSETUP	Q	DON	46.30
16-Feb-2024 1	201,073		739498	06-100-009	Inspect Safety Check	19-Feb-2024 09:17:21	BTRUCK	N	DON	106.09
16-Feb-2024 1	201,073		739498	02-002	Clean Cab & Sheet Metal		BSETUP	Z	WND	714.27
16-Feb-2024 1	201,073		739498	25-051	Remove General Accessories	21-Feb-2024 09:53:43	BSETUP	Z	DON	533.42

Unit No: B2525 Count: 219 45,923.65