

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: N0742 - 2012 JOHN DEERE 35D										
05-Jun-2012 01	2	0	89454	14-063	Install Satellite Communications System	11-Jun-2012 09:48:27	BHVEEQ	Q	DON	274.86
23-Aug-2013 01	2	0	129943	03-063-003	Replace Transceiver - GPS Tracker	23-Aug-2013 00:00:00	BHVEEQ	C	DON	244.36
03-Sep-2013 01	2	0	141127	24-330	Repair Excavator		BVLOFC	F	CAN	0.00
11-Feb-2014 01	731	0	149022	07-100-300	Lubricate Off Road Equip / Field Service	11-Feb-2014 17:00:00	LAKEVL	P	DON	55.48
01-Nov-2014 01	731	0	181689	03-053-008	Replace Hoses & Tubings & Fittings	01-Nov-2014 17:00:00	BVLOFC	F	DON	1,072.46
16-Mar-2016 01	1,747	0	242842	06-100-PMB	Inspect B PMI	16-Mar-2016 07:13:47	LAVSHP	P	DON	16.77
16-Mar-2016 01	1,747	0	242842	07-100-300	Lubricate Off Road Equip / Field Service	16-Mar-2016 07:15:29	LAVSHP	R	DON	22.36
16-Mar-2016 01	1,747	0	242842	03-044-002	Replace Filters	16-Mar-2016 07:14:56	LAVSHP	P	DON	5.59
24-Mar-2016 01	1,747	0	238799	24-330-013	Repair Operator Controls	25-Mar-2016 09:07:23	LAVSHP	B	DON	296.28
25-Mar-2016 01	1,747	0	238961	06-100-PMB	Inspect B PMI	25-Mar-2016 12:50:17	LAVSHP	P	DON	19.65
14-Oct-2016 01	1,859	0	265321	03-365-001	Replace Track	14-Oct-2016 07:00:00	LAVSHP	O	DON	22.36
18-Jan-2017 11	1,915	0	273848	06-100-PMB	Inspect B PMI	18-Jan-2017 15:57:52	ROGSHP	P	DON	160.40
07-Nov-2017 11	1,915	0	311733	35-330-013	Diagnose Operator Controls	07-Nov-2017 15:11:17	MPNFLD	B	DON	1,690.56
03-Jan-2018 01	2,181	0	317883	07-100-PMA	Lubricate A PMI	03-Jan-2018 15:02:24	ROGSHP	P	DON	19.37
03-Jan-2018 01	2,181	0	317883	03-041-007	Replace Filter - Outer	03-Jan-2018 16:10:57	ROGSHP	P	DON	18.05
03-Jan-2018 01	2,181	0	317883	06-400	Inspect Small Equipment Group	03-Jan-2018 14:40:49	ROGSHP	P	DON	2.18
13-Apr-2018 11	2,182	0	331409	03-032-001	Replace Battery	13-Apr-2018 15:05:53	ROGSHP	N	DON	128.64
13-Apr-2018 11	2,182	0	331409	24-330-002	Repair Undercarriage (Tracks&Rollers)	16-Apr-2018 12:16:29	ROGSHP	N	DON	2,093.92
20-Jul-2018 13	2,775	0	344786	07-100-PMA	Lubricate A PMI	20-Jul-2018 13:55:43	ROGSHP	P	DON	36.13
04-Sep-2018 11	2,279	0	350824	03-014-003	Replace Engine Mountings	06-Sep-2018 13:45:51	BHVEEQ	I	DON	326.87
04-Sep-2018 11	2,279	0	350824	03-042-013	Replace Fan Belt	06-Sep-2018 14:07:03	BHVEEQ	I	DON	60.90
04-Sep-2018 11	2,279	0	350824	03-065-008	Replace Line / Tubing Assembly	06-Sep-2018 14:52:15	BHVEEQ	I	DON	413.94
04-Sep-2018 11	2,279	0	350824	03-330-013	Replace Operator Controls	06-Sep-2018 16:00:03	BHVEEQ	I	DON	803.60
04-Sep-2018 11	2,279	0	350824	06-100-PMB	Inspect B PMI	06-Sep-2018 07:18:26	BHVEEQ	P	DON	382.52
04-Sep-2018 11	2,279	0	350824	24-065-004	Repair Cylinder	07-Sep-2018 15:30:06	BHVEEQ	I	DON	884.21
04-Sep-2018 11	2,279	0	350824	06-100-PMC	Inspect C PMI	06-Sep-2018 14:53:28	BHVEEQ	P	DON	40.79
04-Sep-2018 11	2,279	0	350824	06-100-PMA	Inspect A PMI	07-Sep-2018 14:21:51	BHVEEQ	P	DON	0.00
03-Oct-2018 01	2,279	0	354877	15-330	Paint Prep Excavator	16-Oct-2018 09:29:47	BBODY	K	DON	420.71
03-Oct-2018 01	2,279	0	354877	12-330	Refinish Excavator	09-Oct-2018 15:20:41	BBODY	K	DON	338.41

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: N0742 - 2012 JOHN DEERE 35D										
21-Dec-2018 0	2,477	0	365779	24-330-013	Repair Operator Controls	21-Dec-2018 12:12:33	ROGSHP	I	DON	45.24
21-Dec-2018 0	2,477	0	365779	02-330	Clean Excavator	21-Dec-2018 13:16:13	ROGSHP	N	DON	59.41
21-Dec-2018 0	2,477	0	365779	07-100-PMA	Lubricate A PMI	21-Dec-2018 11:41:44	ROGSHP	P	DON	191.73
18-Mar-2019 0	2,544	0	376990	03-033-001	Replace Ignition Switch	19-Mar-2019 11:40:49	LAVSHP	I	DON	251.85
18-Mar-2019 0	2,544	0	376990	03-065-034	Replace Switch - Pressure	19-Mar-2019 13:26:11	LAVSHP	I	DON	90.70
18-Mar-2019 0	2,544	0	376990	06-330	Inspect Excavator	18-Mar-2019 10:18:59	LAVSHP	P	DON	68.10
18-Mar-2019 0	2,544	0	376990	03-002-032	Replace Sidewall & Miscellaneous Trim	25-Mar-2019 13:07:15	LAVSHP	I	DON	29.38
18-Mar-2019 0	2,544	0	376990	03-514-002	Replace Shanks or Teeth	19-Mar-2019 16:08:11	LAVSHP	I	DON	279.92
07-Oct-2019 1	2,728	0	406312	14-520-001	Install D-Ring	07-Oct-2019 17:01:26	ROGSHP	Q	DON	22.70
26-Nov-2019 0	2,750	0	414352	24-034-025	Repair Spot Light - Go Light	26-Nov-2019 14:26:18	ROGSHP	N	DON	307.67
26-Nov-2019 0	2,750	0	414352	38-100-PMB	Service B PMI	26-Nov-2019 11:02:50	ROGSHP	P	DON	108.16
26-Nov-2019 0	2,750	0	414352	06-100-PMB	Inspect B PMI	04-Dec-2019 07:29:34	ROGSHP	P	DON	0.00
18-Dec-2019 0	2,769	0	417437	14-042-009	Install Coolant Pre-Heater- Electrical	18-Dec-2019 19:21:07	ROGSHP	N	DON	177.21
06-Feb-2020 1	2,793	0	425152	06-065-001	Inspect Hydraulic Systems	06-Feb-2020 15:07:29	ROGSHP	N	DON	22.34
06-Feb-2020 1	2,793	0	425152	24-065-007	Repair Hoses & Fittings	06-Feb-2020 16:33:56	ROGSHP	I	DON	155.03
03-Apr-2020 1	2,862	0	434329	03-065-004	Replace Cylinder	07-Apr-2020 13:37:18	ROGSHP	O	DON	1,939.01
03-Apr-2020 1	2,862	0	434329	03-514-002	Replace Shanks or Teeth	07-Apr-2020 14:18:01	ROGSHP	O	DON	27.29
03-Apr-2020 1	2,862	0	434329	11-065-004	Rebuild Cylinder	28-Apr-2020 15:34:30	ROGSHP	Q	DON	734.33
09-Jun-2020 1	2,932	0	444602	24-360-009	Repair Bucket Tooth / Cutting Edge	09-Jun-2020 18:49:10	ROGSHP	O	DON	15.82
17-Jul-2020 14	3,017	0	451220	38-100-PMA	Service A PMI	17-Jul-2020 14:44:51	ME1371	P	DON	46.89
17-Jul-2020 14	3,017	0	451220	06-100-PMA	Inspect A PMI	21-Jul-2020 11:48:03	BHVEYQ	P	DON	0.00
26-Aug-2020 1	3,043	0	458215	03-094-011	Replace Coupler - Quick Disconnect	26-Aug-2020 13:02:05	ROGSHP	N	DON	233.70
08-Oct-2020 1	3,099	0	465556	24-094-011	Repair Coupler - Quick Disconnect	09-Oct-2020 13:08:15	ROGSHP	B	DON	411.36
22-Oct-2020 1		0	468229	24-514	Repair Bucket	22-Oct-2020 15:30:31	ROGSHP	O	DON	142.56
04-Nov-2020 1	3,106	0	470403	24-065-008	Repair Line / Tubing Assembly	05-Nov-2020 08:40:02	ROGSHP	I	DON	122.61
04-Nov-2020 1	3,106	0	470403	06-706-004	Inspect Controls	06-Nov-2020 11:56:43	ROGSHP	O	DON	84.22
04-Nov-2020 1	3,106	0	470403	03-514-002	Replace Shanks or Teeth	05-Nov-2020 09:59:35	ROGSHP	I	DON	49.79
15-Dec-2020 1	3,215	0	477321	24-044	Repair Fuel System	23-Dec-2020 07:19:08	ME1371	B	DON	552.94
15-Dec-2020 1	3,215	0	477321	D0-330	Start Excavator	17-Dec-2020 15:24:21	ME1371	B	DON	26.99

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: N0742 - 2012 JOHN DEERE 35D										
12-Jan-2021 04	3,236	0	481396	01-065-017	Adjust Reservoir/Tank	12-Jan-2021 07:39:42	ROGSHP	I	DON	26.59
12-Jan-2021 04	3,236	0	481396	06-706-001	Inspect Engine	12-Jan-2021 07:34:56	ROGSHP	O	DON	40.26
18-Jan-2021 14	3,244	0	482993	06-044	Inspect Fuel System	19-Jan-2021 10:31:45	ROGSHP	O	DON	252.74
18-Jan-2021 14	3,244	0	482993	06-100-PMA	Inspect A PMI	20-Jan-2021 13:49:36	ROGSHP	P	DON	0.00
18-Jan-2021 14	3,244	0	482993	38-100-PMA	Service A PMI	18-Jan-2021 16:27:08	ROGSHP	P	DON	108.73
18-Jan-2021 14	3,244	0	482993	03-514-002	Replace Shanks or Teeth	19-Jan-2021 10:51:53	ROGSHP	N	DON	50.63
26-Jan-2021 14	3,252	0	484716	03-002-061	Replace Seat Cushion	02-Feb-2021 10:03:36	BHVYEQ	I	DON	866.54
26-Jan-2021 14	3,252	0	484716	03-042-009	Replace Coolant Pre-Heater- Electrical	08-Feb-2021 14:18:43	BHVYEQ	I	DON	55.52
26-Jan-2021 14	3,252	0	484716	03-063-003	Replace Transceiver - GPS Tracker		BHVYEQ	I	CAN	0.00
26-Jan-2021 14	3,252	0	484716	06-330	Inspect Excavator	08-Feb-2021 14:18:40	BHVYEQ	P	DON	332.68
26-Jan-2021 14	3,252	0	484716	03-330-001	Replace Bucket and Attachments	08-Feb-2021 14:18:19	BHVYEQ	I	DON	1,562.50
26-Jan-2021 14	3,252	0	484716	06-100-PMC	Inspect C PMI	24-Feb-2021 06:40:04	BHVYEQ	P	DON	0.00
26-Jan-2021 14	3,252	0	484716	24-002-005	Repair Cowl Panels	08-Feb-2021 14:18:37	BHVYEQ	I	DON	0.00
26-Jan-2021 14	3,252	0	484716	26-515	Weld Blade	08-Feb-2021 12:41:08	BHVYEQ	N	DON	630.73
26-Jan-2021 14	3,252	0	484716	10-330-004	Rebush Boom and Stick Assembly	01-Feb-2021 15:33:59	BHVYEQ	N	DON	2,815.30
26-Jan-2021 14	3,252	0	484716	38-100-PMC	Service C PMI	03-Feb-2021 15:34:52	BHVYEQ	P	DON	489.06
02-Feb-2021 14	3,254	0	486016	02-330	Clean Excavator	03-Feb-2021 07:25:41	BWASH	N	DON	305.18
04-Jun-2021 04	3,317	0	510693	26-514	Weld Bucket	04-Jun-2021 09:29:42	TRK401	O	DON	51.65
04-Jun-2021 04	3,317	0	510693	14-520-001	Install D-Ring	04-Jun-2021 08:54:16	TRK401	O	DON	101.27
08-Jul-2021 14	3,363	0	517307	24-079	Repair Safety Devices	18-Aug-2021 08:51:55	ROGSHP	O	DON	1,211.43
15-Jul-2021 15	3,380	0	518891	06-032-002	Inspect Starter	15-Jul-2021 16:02:06	TRK400	O	DON	91.45
21-Jul-2021 15	3,389	0	519988	01-065-001	Adjust Hydraulic Systems	03-Aug-2021 16:44:37	OTSSHP	P	DON	6.41
21-Jul-2021 15	3,389	0	519988	06-044-007	Inspect Throttle Controls	21-Jul-2021 17:06:38	OTSSHP	O	DON	132.72
21-Jul-2021 15	3,389	0	519988	24-044-007	Repair Throttle Controls	29-Jul-2021 09:01:57	OTSSHP	I	DON	715.95
07-Sep-2021 14	3,452	0	529703	03-032-001	Replace Battery	07-Sep-2021 13:25:20	OTSSHP	N	DON	137.28
07-Sep-2021 14	3,452	0	529703	06-031	Inspect Charging System	07-Sep-2021 13:32:59	OTSSHP	O	DON	5.61
07-Sep-2021 14	3,452	0	529703	24-330-013	Repair Operator Controls	07-Sep-2021 16:57:53	OTSSHP	O	DON	107.88
28-Sep-2021 14	3,483	0	534822	06-100-PMA	Inspect A PMI	28-Sep-2021 14:13:55	ME1371	P	DON	26.56
28-Sep-2021 14	3,483	0	534822	38-100-PMA	Service A PMI	28-Sep-2021 13:58:30	ME1371	P	DON	99.49

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: N0742 - 2012 JOHN DEERE 35D										
06-Oct-2021	3,498	0	537205	03-002-023	Replace Handles - Inner & Outer	06-Oct-2021 13:51:26	ME1371	I	DON	246.44
26-Oct-2021	3,534	0	541956	06-002-004	Inspect Hood	26-Oct-2021 13:16:43	TRK401	O	DON	64.74
26-Oct-2021	3,534	0	541956	24-002-004	Repair Hood	27-Oct-2021 09:41:52	TRK401	I	DON	239.41
26-Oct-2021	3,534	0	541956	03-051-009	Replace Fire Extinguisher	27-Oct-2021 09:45:35	TRK401	I	DON	33.65
03-Nov-2021	3,542	0	543715	03-053-008	Replace Hoses & Tubings & Fittings	04-Nov-2021 09:56:16	OTSSHP	E	DON	474.53
21-Dec-2021	3,599	0	555249	03-065-007	Replace Hoses & Fittings	22-Dec-2021 08:06:00	OTSSHP	B	DON	197.76
02-Feb-2022	3,624	0	563685	03-032-002	Replace Starter	04-Feb-2022 10:07:09	ME1371	B	DON	904.25
02-Feb-2022	3,624	0	563685	03-044-024	Replace Fuel / Water Separator	02-Feb-2022 13:26:40	ME1371	B	DON	30.65
02-Feb-2022	3,624	0	563685	06-032	Inspect Cranking System	02-Feb-2022 14:11:42	ME1371	I	DON	80.74
26-Apr-2022	3,642	0	584470	02-014	Clean Frame	28-Apr-2022 07:31:23	OTSSHP	I	DON	44.22
26-Apr-2022	3,642	0	584470	03-044-003	Replace Fuel Pump	05-May-2022 13:49:12	OTSSHP	I	DON	155.12
26-Apr-2022	3,642	0	584470	06-100-PMA	Inspect A PMI	26-Apr-2022 16:00:20	OTSSHP	P	DON	74.23
26-Apr-2022	3,642	0	584470	03-034-014	Replace Auxiliary Work / Flood Light	26-Apr-2022 17:08:04	OTSSHP	I	DON	144.39
26-Apr-2022	3,642	0	584470	03-514-002	Replace Shanks or Teeth	05-May-2022 13:47:38	OTSSHP	O	DON	47.23
26-Apr-2022	3,642	0	584470	38-100-PMA	Service A PMI	27-Apr-2022 16:01:22	OTSSHP	P	DON	155.66
26-Apr-2022	3,642	0	584470	03-063-003	Replace Transceiver - GPS Tracker	27-Apr-2022 14:19:29	OTSSHP	Q	DON	290.52
05-May-2022	3,642	0	586729	03-514-002	Replace Shanks or Teeth	06-May-2022 08:05:19	TRK401	O	DON	194.75
16-May-2022	3,654	0	588863	03-063-003	Replace Transceiver - GPS Tracker	16-May-2022 16:24:20	OTSSHP	Q	DON	37.68
16-May-2022	3,654	0	588863	24-002-004	Repair Hood	18-May-2022 15:39:32	OTSSHP	O	DON	1,240.06
16-May-2022	3,654	0	588863	24-044-001	Repair Tank - Fuel, Liquid	19-May-2022 10:56:54	OTSSHP	I	DON	59.77
13-Jul-2022	3,654	0	602368	06-044-007	Inspect Throttle Controls	14-Jul-2022 12:19:11	ME1371	B	DON	604.71
13-Jul-2022	3,654	0	602368	24-044-007	Repair Throttle Controls	15-Jul-2022 16:37:27	ME1371	B	DON	2,216.38
05-Dec-2022	3,710	0	636783	06-044-007	Inspect Throttle Controls	05-Dec-2022 12:15:23	TRK400	O	DON	249.02
05-Dec-2022	3,710	0	636783	03-044-007	Replace Throttle Controls	07-Dec-2022 11:41:04	TRK400	I	DON	1,624.95
13-Dec-2022	3,712	0	639135	03-044-007	Replace Throttle Controls	14-Dec-2022 09:01:11	TRK401	O	DON	109.18
13-Dec-2022	3,712	0	639135	95-MSC-004	Travel Travel Time - To/From Job Site	14-Dec-2022 07:53:57	TRK401	B	DON	121.57
23-Mar-2023	3,712	0	661171	01-034-014	Adjust Auxiliary Work / Flood Light	24-Mar-2023 12:03:36	TRK401	I	DON	180.17
23-Mar-2023	3,712	0	661171	06-100-PMA	Inspect A PMI	23-Mar-2023 07:57:31	TRK401	P	DON	63.94
16-Feb-2024	3,712	0	739494	06-330	Inspect Excavator	20-Feb-2024 15:35:56	BHVEEQ	P	DON	90.27

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: N0742 - 2012 JOHN DEERE 35D										
16-Feb-2024 1:	0	739494	02-330		Clean Excavator	20-Feb-2024 12:15:01	BWASH	N	DON	109.76
16-Feb-2024 1:	0	739494	03-041-006		Replace Filter - Inner	20-Feb-2024 14:37:54	BHVYEQ	P	DON	35.15
16-Feb-2024 1:	0	739494	03-041-007		Replace Filter - Outer	20-Feb-2024 15:01:21	BHVYEQ	P	DON	21.81

Unit No: N0742 Count: 119 36,415.17