

# Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
<b>Unit No: B2579 - 2014 F250 EXT CAB</b>										
18-Jul-2014 09	647	0	165828	03-053-012	Replace Pad lock	14-Aug-2014 11:10:41	BSETUP	C	DON	0.00
18-Jul-2014 09	647	0	165828	06-015-004	Inspect Steering Linkage	14-Aug-2014 11:10:10	BTRUCK	I	DON	51.76
18-Jul-2014 09	647	0	165828	06-100-DOT	Inspect DOT Federal Inspection	22-Jul-2014 07:46:47	BTRUCK	P	DON	11.81
18-Jul-2014 09	647	0	165828	09-010-001	Align All Axles	14-Aug-2014 11:07:31	BTRUCK	I	DON	91.44
18-Jul-2014 09	647	0	165828	12-506-001	Refinish Fuel Tank	11-Aug-2014 07:37:59	BSETUP	C	DON	107.38
18-Jul-2014 09	647	0	165828	12-519-002	Refinish Rear Bumper	21-Jul-2014 07:42:37	BSETUP	C	DON	94.24
18-Jul-2014 09	647	0	165828	14-002-003	Install Running Boards / Step Tubes	21-Jul-2014 07:16:08	BSETUP	C	DON	57.20
18-Jul-2014 09	647	0	165828	14-016-005	Install Chassis Spring - Rear	21-Jul-2014 17:00:06	BTRUCK	P	DON	617.39
18-Jul-2014 09	647	0	165828	14-034-006	Install Warning Lamps - Special Application	01-Aug-2014 17:00:25	BSETUP	C	DON	436.53
18-Jul-2014 09	647	0	165828	14-052-003	Install Radio Equipment	21-Jul-2014 10:39:32	BSETUP	C	DON	1,033.71
18-Jul-2014 09	647	0	165828	14-052-014	Install Cellular Telephone Accessories	06-Aug-2014 08:12:09	BSETUP	C	DON	51.37
18-Jul-2014 09	647	0	165828	14-053-005	Install Markings - Vehicle - Decals	21-Jul-2014 10:28:22	BSETUP	C	DON	109.46
18-Jul-2014 09	647	0	165828	14-053-014	Install Floor Mats	21-Jul-2014 10:46:41	BSETUP	C	DON	76.58
18-Jul-2014 09	647	0	165828	14-071-003	Install Side Wall Assembly	01-Aug-2014 17:00:36	BSETUP	C	DON	162.23
18-Jul-2014 09	647	0	165828	14-078-009	Install Mud Flaps and Hanger Brackets	21-Jul-2014 11:27:40	BSETUP	C	DON	45.21
18-Jul-2014 09	647	0	165828	14-078-012	Install Tie-Down - Tarpsaulin	21-Jul-2014 07:30:03	BSETUP	C	DON	55.44
18-Jul-2014 09	647	0	165828	14-079-003	Install Strap, Anti-Static	21-Jul-2014 08:20:18	BSETUP	C	DON	6.87
18-Jul-2014 09	647	0	165828	14-506-001	Install Fuel Tank	12-Aug-2014 17:00:19	BSETUP	C	DON	1,958.06
18-Jul-2014 09	647	0	165828	14-510-002	Install Tool Box	01-Aug-2014 14:35:02	BSETUP	C	DON	278.67
18-Jul-2014 09	647	0	165828	14-517	Install Safety Equipment	01-Aug-2014 13:45:58	BSETUP	C	DON	160.31
18-Jul-2014 09	647	0	165828	14-705	Install Vise	13-Aug-2014 06:25:59	BSETUP	C	DON	40.27
18-Jul-2014 09	647	0	165828	15-506-001	Paint Prep Fuel Tank	11-Aug-2014 07:00:40	BSETUP	C	DON	27.90
18-Jul-2014 09	647	0	165828	21-506-001	Fabricate Fuel Tank	14-Aug-2014 11:10:38	BSETUP	C	DON	149.53
18-Jul-2014 09	647	0	165828	21-705	Fabricate Vise	13-Aug-2014 05:46:51	BWELD	C	DON	187.11
18-Jul-2014 09	647	0	165828	24-034-002	Repair Stop, Tail, Turn & License	13-Aug-2014 10:06:15	BTRUCK	I	DON	87.90
24-Sep-2015 1	22,676	0	215969	06-100-DOT	Inspect DOT Federal Inspection	01-Oct-2015 07:23:17	BTRUCK	P	DON	77.51
24-Sep-2015 1	22,676	0	215969	06-100-PMB	Inspect B PMI	24-Sep-2015 17:04:13	BTRUCK	P	DON	36.35
24-Sep-2015 1	22,676	0	215969	24-002-020	Repair Side Door Mechanism	25-Sep-2015 07:35:14	BTRUCK	I	DON	4.88
24-Sep-2015 1	22,676	0	215969	31-017-001	Rotate Tire - Pneumatic	28-Sep-2015 17:09:22	BTRUCK	I	DON	54.28

# Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B2579 - 2014 F250 EXT CAB										
24-Sep-2015 1	22,676	0	215969	38-045	Service Power Plant	25-Sep-2015 09:30:52	BTRUCK	P	DON	52.22
24-Sep-2015 1	22,676	0	215969	14-079	Install Safety Devices	25-Sep-2015 07:41:38	BTRUCK	I	DON	15.07
24-Sep-2015 1	22,676	0	215969	03-051-009	Replace Fire Extinguisher	25-Sep-2015 08:51:27	BTRUCK	I	DON	44.13
24-Sep-2015 1	22,676	0	215969	03-054-002	Replace Alarm - Reverse Signal	25-Sep-2015 08:25:36	BTRUCK	I	DON	91.06
24-Sep-2015 1	22,676	0	215969	03-034-004	Replace Clearance & Marker Lamps	25-Sep-2015 07:51:26	BTRUCK	I	DON	65.42
24-Sep-2015 1	22,676	0	215969	03-018	Replace Wheels, Rims, Hubs & Bearings	28-Sep-2015 15:53:44	BTRUCK	W	DON	403.01
24-Sep-2015 1	22,676	0	215969	03-519-001	Replace Front Bumper	01-Oct-2015 11:31:24	BTRUCK	A	DON	810.67
24-Sep-2015 1	22,676	0	215969	03-034-001	Replace Headlamps / Fog Lamps	29-Sep-2015 06:16:31	BTRUCK	A	DON	376.19
24-Sep-2015 1	22,676	0	215969	24-071	Repair Body	02-Oct-2015 14:01:08	BBODY	A	DON	230.78
24-Sep-2015 1	22,676	0	215969	12-071	Refinish Body	08-Oct-2015 05:29:58	BBODY	A	DON	302.16
06-Jan-2016 0	22,676	0	227888	14-052-014	Install Cellular Telephone Accessories	02-Mar-2016 08:02:39	BSETUP	I	DON	11.85
06-Jan-2016 0	22,676	0	227888	14-052-015	Install Power Inverter/Converter	07-Jan-2016 06:55:12	ME0546	Q	DON	584.86
29-Sep-2016 0	41,231	0	261418	06-100-DOT	Inspect DOT Federal Inspection	02-Oct-2016 18:06:59	ME1287	P	DON	70.43
02-Mar-2017 0	50,050	0	279421	06-100-PMA	Inspect A PMI	03-Mar-2017 09:37:22	BVLOFC	P	DON	79.58
02-Mar-2017 0	50,050	0	279421	24-052-014	Repair Cellular Telephone Accessories	03-Mar-2017 09:39:57	BVLOFC	O	DON	702.52
19-May-2017 0	57,726	0	289619	03-013-001	Replace Front Brakes & Drums	19-May-2017 06:34:29	BVLOFC	O	DON	321.89
19-May-2017 0	57,726	0	289619	06-100-PMA	Inspect A PMI	19-May-2017 06:34:40	BTRUCK	P	DON	35.02
19-May-2017 0	57,726	0	289619	38-020	Service Drivetrain Group	19-May-2017 06:34:16	BVLOFC	P	DON	280.86
05-Dec-2017 0	79,853	0	320028	06-100-PMA	Inspect A PMI	05-Dec-2017 08:57:00	BVLOFC	P	DON	274.06
29-Mar-2018 1	82,577	0	329218	03-002-024	Replace Glass / Windshield	22-Aug-2018 09:15:57	BTRUCK	O	CAN	0.00
10-Jul-2018 15	95,234	0	343232	24-001	Repair Air Conditioning, Heating & Ventilating	22-Aug-2018 09:17:10	BVLOFC	I	DON	167.51
10-Jul-2018 15	95,234	0	343232	24-033-002	Repair Distributor / Coil Pack	22-Aug-2018 09:17:10	BVLOFC	O	DON	1,230.71
27-Aug-2018 1	101,921	0	349982	06-100-009	Inspect Safety Check		BTRUCK	P	CAN	0.00
27-Aug-2018 1	101,921	0	349982	03-033-002	Replace Distributor / Coil Pack	13-Sep-2018 06:35:32	BTRUCK	I	DON	233.48
27-Aug-2018 1	101,921	0	349982	02-002	Clean Cab & Sheet Metal	07-Sep-2018 17:00:27	BSETUP	N	DON	288.23
27-Aug-2018 1	101,921	0	349982	03-002-024	Replace Glass / Windshield	17-Sep-2018 07:25:23	BTRUCK	I	DON	243.00
27-Aug-2018 1	101,921	0	349982	03-002-035	Replace Windshield Wiper & Washer	12-Sep-2018 10:14:45	BTRUCK	I	DON	23.07
27-Aug-2018 1	101,921	0	349982	06-100-DOT	Inspect DOT Federal Inspection	13-Sep-2018 07:59:03	BTRUCK	P	DON	46.48
27-Aug-2018 1	101,921	0	349982	06-100-PMB	Inspect B PMI	12-Sep-2018 10:14:01	BTRUCK	P	DON	117.86

# Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B2579 - 2014 F250 EXT CAB										
27-Aug-2018 1	101,921		349982	38-045	Service Power Plant	12-Sep-2018 10:14:24	BTRUCK	P	DON	160.82
27-Aug-2018 1	101,921		349982	03-054-002	Replace Alarm - Reverse Signal	13-Sep-2018 06:35:24	BTRUCK	I	DON	86.48
27-Aug-2018 1	101,921		349982	03-079-003	Replace Strap, Anti-Static	12-Sep-2018 10:14:57	BTRUCK	I	DON	6.00
27-Aug-2018 1	101,921		349982	03-013-002	Replace Rear Brakes & Drums	12-Sep-2018 15:16:28	BTRUCK	I	DON	426.77
27-Aug-2018 1	101,921		349982	03-015-004	Replace Steering Linkage	12-Sep-2018 17:04:58	BTRUCK	I	DON	226.65
27-Aug-2018 1	101,921		349982	03-017-001	Replace Tire - Pneumatic	13-Sep-2018 11:30:47	BTIRE	I	DON	899.47
27-Aug-2018 1	101,921		349982	03-013-001	Replace Front Brakes & Drums	12-Sep-2018 12:04:13	BTRUCK	I	DON	434.26
31-Jan-2019 11	118,130		370667	03-052-003	Replace Radio Equipment	02-Feb-2019 09:02:10	BSETUP	I	DON	758.03
31-Jan-2019 11	118,130		370667	02-002	Clean Cab & Sheet Metal	02-Feb-2019 10:08:11	BSETUP	I	DON	110.68
31-Jan-2019 11	118,130		370667	06-100-009	Inspect Safety Check	04-Feb-2019 09:44:20	BTRUCK	P	DON	108.28
31-Jan-2019 11	118,130		370667	06-100-PMB	Inspect B PMI	04-Feb-2019 09:54:01	BTRUCK	P	DON	0.29
31-Jan-2019 11	118,130		370667	14-051-009	Install Fire Extinguisher	04-Feb-2019 09:54:26	BTRUCK	I	DON	124.86
31-Jan-2019 11	118,130		370667	38-045	Service Power Plant	04-Feb-2019 09:54:40	BTRUCK	P	DON	27.73
31-Jan-2019 11	118,130		370667	03-002-035	Replace Windshield Wiper & Washer	04-Feb-2019 09:54:15	BTRUCK	I	DON	22.70
31-Jan-2019 11	118,130		370667	03-034-010	Replace Socket - Trailer Light Cord		BTRUCK	I	DON	
20-Mar-2019 0	122,782		377381	06-100-PMA	Inspect A PMI	20-Mar-2019 15:13:44	MPNSHP	P	DON	106.44
20-Mar-2019 0	122,782		377381	03-045-027	Replace Idler Pulley	20-Mar-2019 14:18:57	MPNSHP	I	WR	161.13
20-Mar-2019 0	122,782		377381	03-022-008	Replace Pinion Seal		MPNSHP	I	WR	11.17
11-Apr-2019 0	125,260		380727	03-016-003	Replace Shock Absorber - Front	11-Apr-2019 15:48:46	MPNSHP	I	DON	205.62
11-Apr-2019 0	125,260		380727	03-022-008	Replace Pinion Seal	11-Apr-2019 13:51:06	MPNSHP	I	DON	75.03
11-Apr-2019 0	125,260		380727	03-033-003	Replace Spark Plugs	12-Apr-2019 10:14:31	MPNSHP	I	DON	485.37
11-Apr-2019 0	125,260		380727	03-034-010	Replace Socket - Trailer Light Cord	12-Apr-2019 14:59:56	MPNSHP	I	DON	143.82
11-Apr-2019 0	125,260		380727	03-053-005	Replace Markings - Vehicle - Decals	11-Apr-2019 15:48:56	MPNSHP	I	DON	4.60
11-Apr-2019 0	125,260		380727	06-100-009	Inspect Safety Check	15-Apr-2019 06:42:49	MPNSHP	P	DON	61.39
11-Apr-2019 0	125,260		380727	06-100-DOT	Inspect DOT Federal Inspection	16-Apr-2019 08:22:31	MPNSHP	P	DON	62.01
11-Apr-2019 0	125,260		380727	35-013	Diagnose Brakes	11-Apr-2019 11:55:31	MPNSHP	O	DON	50.10
29-May-2019 0	128,143		387679	06-100-PMA	Inspect A PMI	29-May-2019 11:22:17	MPNSHP	P	DON	60.48
29-May-2019 0	128,143		387679	38-100-PMA	Service A PMI	29-May-2019 11:57:10	MPNSHP	P	DON	18.79
14-Aug-2019 0	133,973		398522	06-100-PMA	Inspect A PMI	14-Aug-2019 06:57:39	MPNSHP	P	DON	23.92

# Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B2579 - 2014 F250 EXT CAB										
14-Aug-2019 C	133,973		398522	38-100-PMA	Service A PMI	14-Aug-2019 08:05:49	MPNSHP	P	DON	71.35
26-Aug-2019 I	135,186		400422	02-002	Clean Cab & Sheet Metal	01-Nov-2019 05:39:14	BSETUP	N	DON	32.14
29-Oct-2019 O	140,272		409983	06-100-PMA	Inspect A PMI	29-Oct-2019 09:29:09	MPNSHP	P	DON	83.62
29-Oct-2019 O	140,272		409983	38-100-PMA	Service A PMI	29-Oct-2019 09:34:16	MPNSHP	P	DON	20.80
29-Oct-2019 O	140,272		409983	06-040	Inspect Engine / Motor Systems Group		MPNSHP	I	WR	0.00
17-Dec-2019 I	144,668		417333	03-031-001	Replace Generator/Alternator	30-Dec-2019 11:56:29	MPNSHP	I	DON	549.63
17-Dec-2019 I	144,668		417333	06-100-PMA	Inspect A PMI	07-Jan-2020 16:02:27	MPNSHP	P	DON	0.00
17-Dec-2019 I	144,668		417333	38-100-PMA	Service A PMI	07-Jan-2020 16:02:47	MPNSHP	P	DON	44.29
20-Mar-2020 O	151,817		432078	03-013-001	Replace Front Brakes & Drums	24-Apr-2020 14:47:24	MPNSHP	I	DON	910.40
20-Mar-2020 O	151,817		432078	03-013-002	Replace Rear Brakes & Drums	20-Mar-2020 11:41:37	MPNSHP	I	DON	257.35
20-Mar-2020 O	151,817		432078	06-100-PMA	Inspect A PMI	20-Mar-2020 08:48:45	MPNSHP	P	DON	38.93
20-Mar-2020 O	151,817		432078	38-100-PMA	Service A PMI	20-Mar-2020 10:02:17	MPNSHP	P	DON	460.13
20-Mar-2020 O	151,817		432078	03-017-001	Replace Tire - Pneumatic	29-May-2020 06:27:59	MPNSHP	N	DON	1,157.18
30-Mar-2020 O	151,911		433452	06-100-DOT	Inspect DOT Federal Inspection	30-Mar-2020 09:00:38	MPNFLD	P	DON	35.72
29-May-2020 C	156,741		442769	06-100-PMA	Inspect A PMI	29-May-2020 07:31:30	MPNSHP	P	DON	15.58
29-May-2020 C	156,741		442769	38-100-PMA	Service A PMI	29-May-2020 08:23:00	MPNSHP	P	DON	64.92
15-Jun-2020 I	157,796		445551	03-021-109	Replace Universal Joint	17-Jul-2020 07:11:46	MPNSHP	N	DON	1,007.38
15-Jun-2020 I	157,796		445551	03-013-001	Replace Front Brakes & Drums	17-Jul-2020 07:11:46	MPNSHP	I	DON	330.32
07-Aug-2020 C	161,954		454860	03-063-003	Replace Transceiver - GPS Tracker	20-Aug-2020 13:01:37	MPNSHP	I	DON	242.59
07-Aug-2020 C	161,954		454860	06-100-PMA	Inspect A PMI	07-Aug-2020 10:32:08	MPNSHP	P	DON	22.28
07-Aug-2020 C	161,954		454860	38-100-PMA	Service A PMI	20-Aug-2020 13:01:33	MPNSHP	P	DON	33.21
19-Mar-2021 I	167,193		495401	02-002	Clean Cab & Sheet Metal	05-Apr-2021 16:09:06	BSETUP	I	DON	699.64
19-Mar-2021 I	167,193		495401	03-002-035	Replace Windshield Wiper & Washer	22-Mar-2021 12:00:05	BTRUCK	I	DON	22.49
19-Mar-2021 I	167,193		495401	03-053-005	Replace Markings - Vehicle - Decals	05-Apr-2021 12:30:05	BSETUP	I	DON	232.45
19-Mar-2021 I	167,193		495401	03-072-006	Replace Door Latch Mechanism	22-Mar-2021 16:12:36	BTRUCK	I	DON	369.67
19-Mar-2021 I	167,193		495401	06-100-009	Inspect Safety Check	22-Mar-2021 10:58:17	BTRUCK	P	DON	150.81
19-Mar-2021 I	167,193		495401	06-100-DOT	Inspect DOT Federal Inspection	29-Mar-2021 08:24:22	BTRUCK	P	DON	50.67
19-Mar-2021 I	167,193		495401	06-100-PMB	Inspect B PMI	29-Mar-2021 07:07:29	BTRUCK	P	DON	17.87
19-Mar-2021 I	167,193		495401	14-051-009	Install Fire Extinguisher	22-Mar-2021 11:46:54	BTRUCK	Q	DON	153.16

# Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B2579 - 2014 F250 EXT CAB										
19-Mar-2021	1	167,193	495401	14-052-015	Install Power Inverter/Converter	02-Apr-2021 08:21:48	BSETUP	I	DON	657.15
19-Mar-2021	1	167,193	495401	14-055	Install Cargo Handling, Restraints & Lift System	30-Mar-2021 13:11:06	BSETUP	I	DON	117.41
19-Mar-2021	1	167,193	495401	24-001-010	Repair Compressor Assembly - Air Cond	23-Mar-2021 06:20:18	BTRUCK	I	DON	476.31
19-Mar-2021	1	167,193	495401	24-013-001	Repair Front Brakes & Drums	25-Mar-2021 09:39:26	BTRUCK	I	DON	612.45
19-Mar-2021	1	167,193	495401	24-016-006	Repair Shock Absorber - Rear	23-Mar-2021 07:07:13	BTRUCK	I	DON	152.97
19-Mar-2021	1	167,193	495401	24-027-029	Repair Oil Pump Assembly	26-Mar-2021 08:24:39	BTRUCK	I	DON	1,052.38
19-Mar-2021	1	167,193	495401	24-043-002	Repair Exhaust Manifold	24-Mar-2021 14:57:21	BTRUCK	I	DON	526.69
19-Mar-2021	1	167,193	495401	24-044-016	Repair Tank - Fuel Auxiliary	22-Mar-2021 11:32:48	BTRUCK	I	DON	27.04
19-Mar-2021	1	167,193	495401	24-052-003	Repair Radio Equipment	24-Mar-2021 11:53:29	BTRUCK	Q	DON	155.67
19-Mar-2021	1	167,193	495401	24-519-001	Repair Front Bumper	23-Mar-2021 06:40:59	BTRUCK	I	DON	13.63
19-Mar-2021	1	167,193	495401	25-044-001	Remove Tank - Fuel, Liquid	30-Mar-2021 10:10:44	BSETUP	I	DON	194.20
19-Mar-2021	1	167,193	495401	31-017-001	Rotate Tire - Pneumatic	26-Mar-2021 10:05:26	BTRUCK	I	DON	66.42
19-Mar-2021	1	167,193	495401	38-045	Service Power Plant	22-Mar-2021 13:57:00	BTRUCK	P	DON	113.29
12-Apr-2021	1	167,193	499942	03-052-003	Replace Radio Equipment	12-Apr-2021 12:09:35	ELEC01	Q	DON	1,024.31
17-Mar-2022	1	177,828	575342	02-002	Clean Cab & Sheet Metal	10-May-2022 15:29:11	BSETUP	N	DON	543.47
17-Mar-2022	1	177,828	575342	03-002-011	Replace Cab Accessories - Interior	24-Mar-2022 08:59:12	BTRUCK	I	DON	18.91
17-Mar-2022	1	177,828	575342	03-017-001	Replace Tire - Pneumatic	02-May-2022 10:43:15	BTRUCK	I	DON	1,106.43
17-Mar-2022	1	177,828	575342	03-032-001	Replace Battery	02-Apr-2022 05:03:33	BTRUCK	O	DON	127.96
17-Mar-2022	1	177,828	575342	03-033-002	Replace Distributor / Coil Pack	02-May-2022 05:51:06	BTRUCK	I	DON	147.98
17-Mar-2022	1	177,828	575342	03-034-002	Replace Stop, Tail, Turn & License	02-May-2022 16:50:33	BTRUCK	I	DON	76.55
17-Mar-2022	1	177,828	575342	03-053-016	Replace Cover - Seat	24-Mar-2022 10:32:01	BTRUCK	I	DON	192.08
17-Mar-2022	1	177,828	575342	03-079-009	Replace Tape - Reflective, Conspicuity	02-May-2022 10:24:57	BTRUCK	I	DON	9.31
17-Mar-2022	1	177,828	575342	06-100-009	Inspect Safety Check	18-Mar-2022 11:46:43	BTRUCK	I	DON	92.13
17-Mar-2022	1	177,828	575342	06-100-DOT	Inspect DOT Federal Inspection	02-May-2022 13:50:13	BTRUCK	P	DON	62.83
17-Mar-2022	1	177,828	575342	06-100-PMB	Inspect B PMI	18-Mar-2022 12:52:35	BTRUCK	P	DON	16.19
17-Mar-2022	1	177,828	575342	12-519-002	Refinish Rear Bumper	10-May-2022 15:58:18	BSETUP	K	DON	159.90
17-Mar-2022	1	177,828	575342	14-051-009	Install Fire Extinguisher	24-Mar-2022 08:38:47	BTRUCK	Q	DON	161.66
17-Mar-2022	1	177,828	575342	24-002-022	Repair Rear Door Mechanism	02-May-2022 09:50:21	BTRUCK	I	DON	72.46
17-Mar-2022	1	177,828	575342	24-018-001	Repair Front Axle Hubs & Bearings	02-May-2022 06:59:03	BTRUCK	I	DON	315.29

# Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B2579 - 2014 F250 EXT CAB										
17-Mar-2022	1	177,828	575342	24-025	Repair Transfer Case	02-May-2022 10:10:49	BTRUCK	O	DON	13.49
17-Mar-2022	1	177,828	575342	24-034-006	Repair Warning Lamps - Special Application	02-May-2022 14:12:39	BTRUCK	O	DON	143.62
17-Mar-2022	1	177,828	575342	38-100-PMA	Service A PMI	02-May-2022 08:00:24	BTRUCK	P	DON	82.52
05-Dec-2022	1	196,316	636991	06-100-009	Inspect Safety Check	06-Dec-2022 08:01:58	BTRUCK	P	DON	121.39
05-Dec-2022	1	196,316	636991	06-100-PMB	Inspect B PMI	09-Dec-2022 15:18:56	BTRUCK	P	DON	66.23
05-Dec-2022	1	196,316	636991	38-100-PMA	Service A PMI	09-Dec-2022 17:05:21	BTRUCK	P	DON	130.28
05-Dec-2022	1	196,316	636991	03-001-008	Replace Motor - Blower	13-Dec-2022 08:15:59	BTRUCK	I	DON	199.55
05-Dec-2022	1	196,316	636991	03-013-002	Replace Rear Brakes & Drums	12-Dec-2022 14:45:10	BTRUCK	I	DON	585.13
05-Dec-2022	1	196,316	636991	03-015-004	Replace Steering Linkage	14-Dec-2022 09:34:48	BTRUCK	I	DON	404.03
05-Dec-2022	1	196,316	636991	03-033-002	Replace Distributor / Coil Pack	12-Dec-2022 08:37:06	BTRUCK	I	DON	139.48
05-Dec-2022	1	196,316	636991	03-034-003	Replace Signal, Parking, Backup Lamps	12-Dec-2022 07:11:55	BTRUCK	I	DON	122.02
05-Dec-2022	1	196,316	636991	03-002-024	Replace Glass / Windshield	13-Dec-2022 07:06:36	BTRUCK	I	DON	309.69
05-Dec-2022	1	196,316	636991	14-018-012	Install Cap - Hub	12-Dec-2022 07:24:30	BTRUCK	I	DON	88.63
05-Dec-2022	1	196,316	636991	14-051-009	Install Fire Extinguisher	12-Dec-2022 08:03:46	BTRUCK	Q	DON	214.21
05-Dec-2022	1	196,316	636991	24-001-002	Repair Heating & Ventilating	13-Dec-2022 10:38:53	BTRUCK	I	DON	320.16
05-Dec-2022	1	196,316	636991	06-100-DOT	Inspect DOT Federal Inspection	19-Dec-2022 07:57:36	BTRUCK	P	DON	49.09
05-Dec-2022	1	196,316	636991	24-002-035	Repair Windshield Wiper & Washer	12-Dec-2022 17:00:57	BTRUCK	I	DON	134.78
05-Dec-2022	1	196,316	636991	24-002-068	Repair Service Body / Utility Box	13-Dec-2022 13:34:04	BTRUCK	I	DON	289.43
05-Dec-2022	1	196,316	636991	24-034-002	Repair Stop, Tail, Turn & License	12-Dec-2022 10:43:43	BTRUCK	I	DON	33.59
05-Dec-2022	1	196,316	636991	31-017-001	Rotate Tire - Pneumatic	12-Dec-2022 16:23:38	BTRUCK	P	DON	19.38
05-Dec-2022	1	196,316	636991	24-013-034	Repair Parking Brake - Complete	12-Dec-2022 16:24:41	BTRUCK	I	DON	128.78
05-Dec-2022	1	196,316	636991	24-052-015	Repair Power Inverter/Converter	14-Dec-2022 08:22:51	BTRUCK	I	DON	286.36
05-Dec-2022	1	196,316	636991	24-002-020	Repair Side Door Mechanism	19-Dec-2022 07:57:52	BTRUCK	I	DON	56.02
27-Dec-2022	0	196,350	641367	02-002	Clean Cab & Sheet Metal	03-Jan-2023 08:58:45	BSETUP	N	DON	337.71
27-Dec-2022	0	196,350	641367	12-002-003	Refinish Running Boards / Step Tubes	03-Jan-2023 07:02:59	BSETUP	I	DON	15.84
27-Dec-2022	0	196,350	641367	03-052-014	Replace Cellular Telephone Accessories	03-Jan-2023 11:21:21	BSETUP	I	DON	23.10
28-Mar-2023	0	196,524	662399	24-032	Repair Cranking System	30-Mar-2023 06:28:32	BTRUCK	O	DON	259.35
29-Apr-2023	1	197,714	671015	24-017-001	Repair Tire - Pneumatic	02-May-2023 07:50:01	BVLOFC	B	DON	56.48
14-Jul-2023	10	204,111	688109	03-002-024	Replace Glass / Windshield	26-Jul-2023 13:26:01	BVLOFC	E	DON	338.45

# Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
<b>Unit No: B2579 - 2014 F250 EXT CAB</b>										
14-Jul-2023	10	204,111	688109	06-100-PMA	Inspect A PMI	26-Jul-2023 13:26:01	BVLOFC	P	DON	0.00
14-Jul-2023	10	204,111	688109	38-100-PMA	Service A PMI	26-Jul-2023 13:26:01	BVLOFC	P	DON	110.82
01-Apr-2024	0	223,494	749324	24-032-001	Repair Battery		BTRUCK	N	WND	14.37
01-Apr-2024	0	223,494	749324	38-100-PMA	Service A PMI		BTRUCK	P	CAN	0.00
01-Apr-2024	0	223,494	749324	06-100-DOT	Inspect DOT Federal Inspection		BTRUCK	P	CAN	0.00
01-Apr-2024	0	223,494	749324	06-100-PMB	Inspect B PMI	02-Apr-2024 06:45:32	BTRUCK	P	DON	126.21
01-Apr-2024	0	223,494	749324	03-002-024	Replace Glass / Windshield	11-Apr-2024 07:49:15	BTRUCK	N	DON	332.33
01-Apr-2024	0	223,494	749324	25-051	Remove General Accessories		BSETUP	Z	WND	601.31
01-Apr-2024	0	223,494	749324	02-002	Clean Cab & Sheet Metal		BSETUP	Z	WND	736.00

Unit No: B2579

Count: 183

40,319.83