

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: N1073 - 2015 CAT 336FL XE										
25-Aug-2016 1	234	0	257156	14-051-009	Install Fire Extinguisher	25-Aug-2016 17:00:17	BHVYEQ	Q	DON	35.44
25-Aug-2016 1	234	0	257156	14-063-003	Install Transceiver - GPS Tracker	25-Aug-2016 16:13:00	BHVYEQ	Q	DON	85.63
08-Nov-2016 1	234	0	265958	02-330	Clean Excavator	09-Nov-2016 14:34:08	BWASH	J	DON	275.19
03-Feb-2017 0	674	0	276019	03-514-002	Replace Shanks or Teeth	01-Mar-2017 05:13:18	BHVYEQ	E	DON	1,066.43
03-Feb-2017 0	674	0	276019	14-052-005	Install Transmitter - CB	06-Feb-2017 15:00:34	BHVYEQ	J	DON	96.61
03-Feb-2017 0	674	0	276019	06-100-PMA	Inspect A PMI	28-Feb-2017 14:12:33	BHVYEQ	P	DON	529.53
10-May-2017 1	864	0	288467	03-514-002	Replace Shanks or Teeth	10-May-2017 15:26:18	BHVYEQ	E	DON	1,070.19
10-May-2017 1	864	0	288467	24-043-023	Repair Tank - DEF	10-May-2017 15:23:57	BHVYEQ	W	DON	102.74
18-May-2017 1	887	0	289419	03-002-024	Replace Glass / Windshield	19-May-2017 08:34:58	BHVYEQ	E	DON	210.58
29-Jun-2017 1	1,027	0	295113	03-111-006	Replace Shields and Guards	08-Jul-2017 07:29:38	BHVYEQ	I	DON	1,310.83
29-Jun-2017 1	1,027	0	295113	06-100-PMB	Inspect B PMI	29-Jun-2017 15:23:10	BHVYEQ	P	DON	2,551.15
29-Jun-2017 1	1,027	0	295113	24-330-015	Repair Quik-Attach Assembly	08-Jul-2017 07:30:56	BHVYEQ	W	DON	0.00
15-Aug-2017 1	1,027	0	301074	34-065-007	Reseal Hoses & Fittings	15-Aug-2017 09:45:30	BHVYEQ	I	DON	412.38
06-Sep-2017 1	1,350	0	303870	06-100-PMA	Inspect A PMI	06-Sep-2017 10:42:17	BHVYEQ	P	DON	656.08
10-Oct-2017 1	1,615	0	308342	06-100-PMA	Inspect A PMI	10-Oct-2017 15:17:55	BHVYEQ	P	DON	756.83
05-Jan-2018 1	1,778	0	318449	03-518-001	Replace Steps	11-Jan-2018 16:00:00	BHVYEQ	I	DON	528.42
05-Jan-2018 1	1,778	0	318449	06-100-PMA	Inspect A PMI	09-Jan-2018 09:31:37	BHVYEQ	P	DON	402.99
05-Jan-2018 1	1,778	0	318449	06-100-PMB	Inspect B PMI	15-Jan-2018 11:50:42	BHVYEQ	P	DON	247.21
20-Jun-2018 1	1,778	0	340535	03-065-007	Replace Hoses & Fittings	26-Jun-2018 14:54:03	BHVYEQ	O	DON	162.24
31-Jul-2018 07	2,010	0	346052	06-100-PMA	Inspect A PMI	31-Jul-2018 07:53:42	BHVYEQ	P	DON	1,306.60
28-Sep-2018 1	2,010	0	354271	03-001-016	Replace Filter - Cab Ventilation	01-Oct-2018 05:29:32	BHVYEQ	N	DON	41.23
28-Sep-2018 1	2,010	0	354271	03-041-006	Replace Filter - Inner	01-Oct-2018 05:29:32	BHVYEQ	N	DON	23.05
28-Sep-2018 1	2,010	0	354271	03-041-007	Replace Filter - Outer	01-Oct-2018 05:29:32	BHVYEQ	N	DON	47.39
28-Sep-2018 1	2,010	0	354271	03-044-002	Replace Filters	01-Oct-2018 05:29:32	BHVYEQ	N	DON	46.99
28-Sep-2018 1	2,010	0	354271	03-514-002	Replace Shanks or Teeth	01-Oct-2018 05:29:27	BHVYEQ	E	DON	1,871.12
11-Dec-2018 0	2,010	0	363807	24-111-011	Repair Track Pad	17-Dec-2018 08:34:59	BHVYEQ	O	DON	29.16
11-Feb-2019 1	2,660	0	372094	02-330	Clean Excavator	19-Feb-2019 14:57:14	BWASH	N	DON	293.19
11-Feb-2019 1	2,660	0	372094	03-111-011	Replace Track Pad	20-Feb-2019 13:34:13	BHVYEQ	I	DON	193.17
11-Feb-2019 1	2,660	0	372094	06-100-PMA	Inspect A PMI	12-Feb-2019 08:25:18	BHVYEQ	P	DON	266.40

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: N1073 - 2015 CAT 336FL.XE										
11-Feb-2019 1	2,660	0	372094	06-100-PMB	Inspect B PMI	20-Feb-2019 14:14:19	BHVEQ	P	DON	947.67
11-Feb-2019 1	2,660	0	372094	06-100-PMC	Inspect C PMI	20-Feb-2019 14:57:04	BHVEQ	P	DON	31.73
11-Feb-2019 1	2,660	0	372094	14-042-009	Install Coolant Pre-Heater- Electrical	13-Feb-2019 09:49:58	BHVEQ	I	DON	292.53
02-Apr-2019 1	2,670	0	379331	24-049-001	Repair ECM Fault Code	04-Apr-2019 04:41:27	BHVEQ	W	DON	185.25
02-Apr-2019 1	2,670	0	379331	24-063-003	Repair Transceiver - GPS Tracker	03-Apr-2019 12:35:44	BHVEQ	N	DON	257.31
02-Apr-2019 1	2,670	0	379331	34-330-003	Reseal Final Drive	04-Apr-2019 04:44:55	BHVEQ	W	DON	0.00
02-Apr-2019 1	2,670	0	379331	37-049-002	Calibrate ECM Module	04-Apr-2019 04:43:39	BHVEQ	W	DON	0.00
23-Apr-2019 1	2,670	0	382505	14-330-001	Install Bucket and Attachments	23-Apr-2019 16:28:57	BHVEQ	Q	DON	124.40
14-May-2019 1	2,703	0	385769	37-330-001	Calibrate Bucket and Attachments	14-May-2019 13:49:53	BHVEQ	N	DON	1,587.12
13-Jun-2019 1	2,703	0	390087	24-514	Repair Bucket	14-Jun-2019 09:54:41	BHVEQ	N	DON	139.88
13-Jun-2019 1	2,703	0	390087	03-065-007	Replace Hoses & Fittings	25-Jun-2019 07:20:34	BVLOFC	N	DON	162.64
25-Jun-2019 0	2,950	0	391553	06-100-PMB	Inspect B PMI	25-Jun-2019 06:45:26	MONSHP	P	DON	0.00
25-Jun-2019 0	2,950	0	391553	38-100-PMB	Service B PMI	25-Jun-2019 06:47:25	MONSHP	P	DON	1,873.52
01-Aug-2019 1	3,106	0	396892	06-100-PMA	Inspect A PMI	14-Aug-2019 10:20:52	BHVEQ	P	DON	316.24
01-Aug-2019 1	3,106	0	396892	38-100-PMA	Service A PMI	02-Aug-2019 08:47:52	BHVEQ	P	DON	223.00
01-Aug-2019 1	3,106	0	396892	03-065-007	Replace Hoses & Fittings	05-Aug-2019 11:18:01	BHVEQ	I	DON	1,112.70
01-Aug-2019 1	3,106	0	396892	03-002-024	Replace Glass / Windshield	02-Aug-2019 10:51:24	BHVEQ	I	DON	374.00
06-Aug-2019 1	3,106	0	397475	02-330	Clean Excavator	13-Aug-2019 10:51:53	BWASH	N	DON	1,581.97
22-Aug-2019 C	3,106	0	399816	03-002-024	Replace Glass / Windshield	22-Aug-2019 19:02:16	BHVEQ	E	DON	747.57
11-Dec-2019 0	3,161	0	416296	02-002	Clean Cab & Sheet Metal	08-Jan-2020 08:03:20	BHVEQ	N	DON	52.40
11-Dec-2019 0	3,161	0	416296	03-043-022	Replace Injector - DEF	12-Dec-2019 07:14:08	BHVEQ	N	DON	442.04
11-Dec-2019 0	3,161	0	416296	03-049-004	Replace ECM Sensor	02-Jan-2020 13:01:38	BHVEQ	N	DON	181.75
11-Dec-2019 0	3,161	0	416296	03-051-009	Replace Fire Extinguisher	11-Dec-2019 13:09:15	BHVEQ	N	DON	33.45
11-Dec-2019 0	3,161	0	416296	06-330	Inspect Excavator	09-Jan-2020 14:57:31	BHVEQ	N	DON	148.14
11-Dec-2019 0	3,161	0	416296	24-063-003	Repair Transceiver - GPS Tracker	09-Jan-2020 14:48:53	BHVEQ	Q	DON	0.00
11-Dec-2019 0	3,161	0	416296	34-065-020	Reseal Control Valve	09-Jan-2020 15:21:26	BHVEQ	N	DON	4,235.77
24-Apr-2020 1	0	0	437864	03-032-001	Replace Battery	24-Apr-2020 17:02:15	BHVEQ	I	DON	497.23
08-May-2020 C	0	0	439844	24-065-007	Repair Hoses & Fittings	08-May-2020 06:30:02	BHVEQ	B	DON	52.40
09-Jun-2020 0	0	0	444652	24-065-007	Repair Hoses & Fittings	11-Jun-2020 09:32:34	BHVEQ	B	DON	358.60

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: N1073 - 2015 CAT 336FL.XE										
05-Oct-2020 01	0	464733	02-330	02-330	Clean Excavator	12-Oct-2020 14:40:24	BWASH	N	DON	481.34
05-Oct-2020 01	0	464733	06-100-PMA	06-100-PMA	Inspect A PMI	05-Oct-2020 11:11:46	BHVYEQ	P	DON	154.36
05-Oct-2020 01	0	464733	24-019-001	24-019-001	Repair Reservoir & Lines	06-Oct-2020 11:34:57	BHVYEQ	I	DON	72.57
05-Oct-2020 01	0	464733	38-100-PMA	38-100-PMA	Service A PMI	05-Oct-2020 16:06:01	BHVYEQ	P	DON	486.46
16-Nov-2020 1	0	472380	03-043-020	03-043-020	Replace Pump - DEF	04-Dec-2020 05:28:57	BHVYEQ	B	DON	1,716.49
16-Nov-2020 1	0	472380	24-514-002	24-514-002	Repair Shanks or Teeth	16-Nov-2020 15:49:17	BHVYEQ	O	DON	69.44
16-Nov-2020 1	0	472380	03-044-002	03-044-002	Replace Filters	04-Dec-2020 05:28:59	BHVYEQ	P	DON	40.94
04-Feb-2021 1	0	486500	38-100-PMB	38-100-PMB	Service B PMI	08-Feb-2021 16:05:15	BHVYEQ	P	DON	1,792.02
04-Feb-2021 1	0	486500	06-100-PMB	06-100-PMB	Inspect B PMI	09-Feb-2021 16:42:26	BHVYEQ	P	DON	216.81
04-Feb-2021 1	0	486500	03-518-001	03-518-001	Replace Steps	08-Feb-2021 13:18:35	BHVYEQ	I	DON	1,227.97
09-Feb-2021 0	0	487056	02-330	02-330	Clean Excavator	10-Feb-2021 08:24:29	BWASH	N	DON	247.13
20-Jul-2021 14	0	519726	03-065-007	03-065-007	Replace Hoses & Fittings	30-Jul-2021 00:00:00	BVLOFC	O	DON	730.34
20-Jul-2021 14	0	519726	95-MSC	95-MSC	Travel Miscellaneous	30-Jul-2021 00:00:00	BVLOFC	N	DON	323.61
16-Feb-2022 1	3,204	567483	03-063-003	03-063-003	Replace Transceiver - GPS Tracker	16-Feb-2022 11:37:19	ELEC02	Q	DON	311.44
04-Mar-2022 0	3,987	572109	02-330	02-330	Clean Excavator	09-Mar-2022 17:00:06	BWASH	N	DON	505.61
04-Mar-2022 0	3,987	572109	06-100-PMB	06-100-PMB	Inspect B PMI	08-Mar-2022 12:42:16	BHVYEQ	P	DON	217.30
04-Mar-2022 0	3,987	572109	06-100-PMC	06-100-PMC	Inspect C PMI	23-Mar-2022 10:53:26	BHVYEQ	P	DON	42.89
04-Mar-2022 0	3,987	572109	18-042	18-042	Test Cooling System	07-Mar-2022 09:53:33	BHVYEQ	I	DON	100.41
04-Mar-2022 0	3,987	572109	38-100-PMB	38-100-PMB	Service B PMI	07-Mar-2022 16:43:50	BHVYEQ	N	DON	642.02
04-Mar-2022 0	3,987	572109	38-100-PMC	38-100-PMC	Service C PMI	08-Mar-2022 12:43:07	BHVYEQ	N	DON	42.34
24-Mar-2022 1	3,987	576983	03-514-002	03-514-002	Replace Shanks or Teeth	29-Mar-2022 14:29:27	BHVYEQ	N	DON	2,053.44
24-Mar-2022 1	3,987	576983	26-514-001	26-514-001	Weld Ears	29-Mar-2022 10:50:16	BHVYEQ	N	DON	115.60
24-Mar-2022 1	3,987	576983	37-063-008	37-063-008	Calibrate Transceiver - GPS Grade Control	04-Apr-2022 09:50:34	BHVYEQ	N	DON	1,148.17
12-Apr-2022 1	3,987	581419	02-002-044	02-002-044	Clean Cab - Complete	13-Apr-2022 13:22:29	BHVYEQ	I	DON	65.30
12-Apr-2022 1	3,987	581419	24-111-011	24-111-011	Repair Track Pad	13-Apr-2022 11:22:50	BHVYEQ	O	DON	147.95
20-Jun-2022 1:	3,987	597195	03-052-005	03-052-005	Replace Transmitter - CB	20-Jun-2022 15:17:04	BHVYEQ	Q	DON	235.42
23-Jun-2022 01	3,987	598216	06-100-PMB	06-100-PMB	Inspect B PMI	23-Jun-2022 14:05:34	TRK001	P	DON	97.43
23-Jun-2022 01	3,987	598246	38-100-PMA	38-100-PMA	Service A PMI	24-Jun-2022 09:36:59	TRK001	N	DON	318.41
23-Jun-2022 01	3,987	598246	06-100-PMA	06-100-PMA	Inspect A PMI	24-Jun-2022 09:37:59	TRK001	P	DON	0.00

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: N1073 - 2015 CAT 336FL XE										
28-Jun-2022 11	3,987	0	599105	03-052-005	Replace Transmitter - CB	28-Jun-2022 11:11:19	BHVYEQ	Q	DON	117.72
09-Sep-2022 01	3,987	0	614967	38-100-PMA	Service A PMI	13-Sep-2022 12:52:39	TRK001	N	DON	282.45
09-Sep-2022 01	3,987	0	614967	06-100-PMA	Inspect A PMI	13-Sep-2022 12:54:25	SCHED	P	DON	0.00
02-Mar-2023 01	4,886	0	656218	02-043-009	Clean Diesel Particulate Filter - DPF	08-Mar-2023 13:22:12	BHVYEQ	N	DON	784.18
02-Mar-2023 01	4,886	0	656218	02-330	Clean Excavator	21-Apr-2023 08:35:42	BWASH	N	DON	522.25
02-Mar-2023 01	4,886	0	656218	03-002-035	Replace Windshield Wiper & Washer	10-Mar-2023 06:01:16	BHVYEQ	I	DON	75.64
02-Mar-2023 01	4,886	0	656218	03-002-060	Replace Seat Belt	03-Apr-2023 08:11:05	BHVYEQ	I	DON	356.00
02-Mar-2023 01	4,886	0	656218	03-032-001	Replace Battery	10-Mar-2023 12:02:29	BHVYEQ	I	DON	506.71
02-Mar-2023 01	4,886	0	656218	03-033-003	Replace Spark Plugs	07-Mar-2023 12:02:02	BHVYEQ	I	DON	75.74
02-Mar-2023 01	4,886	0	656218	03-045-023	Replace Engine Belts	06-Mar-2023 12:03:41	BHVYEQ	I	DON	321.91
02-Mar-2023 01	4,886	0	656218	03-065-007	Replace Hoses & Fittings	14-Mar-2023 06:40:42	BHVYEQ	I	DON	5,392.33
02-Mar-2023 01	4,886	0	656218	03-111-002	Replace Roller	07-Mar-2023 10:27:30	BHVYEQ	I	DON	757.29
02-Mar-2023 01	4,886	0	656218	03-111-004	Replace Tensioner	07-Apr-2023 15:57:37	BHVYEQ	I	DON	6,151.58
02-Mar-2023 01	4,886	0	656218	06-100-PMB	Inspect B PMI	13-Jun-2023 09:54:36	BHVYEQ	P	DON	841.20
02-Mar-2023 01	4,886	0	656218	14-043-009	Install Diesel Particulate Filter - DPF	10-Mar-2023 10:10:34	BHVYEQ	I	DON	231.96
02-Mar-2023 01	4,886	0	656218	14-065-004	Install Cylinder	03-Apr-2023 08:10:53	BHVYEQ	I	DON	671.42
02-Mar-2023 01	4,886	0	656218	24-002-037	Repair Seat Assembly	16-Mar-2023 13:30:25	BHVYEQ	I	DON	589.54
02-Mar-2023 01	4,886	0	656218	24-052-013	Repair Antenna and Mounting	17-Mar-2023 11:15:38	BHVYEQ	I	DON	160.12
02-Mar-2023 01	4,886	0	656218	24-065-004	Repair Cylinder	03-Apr-2023 04:39:56	BHVYEQ	I	DON	3,546.63
02-Mar-2023 01	4,886	0	656218	24-330-020	Repair Bucket Linkage	03-Apr-2023 08:10:44	BHVYEQ	I	DON	8,068.86
02-Mar-2023 01	4,886	0	656218	25-043-009	Remove Diesel Particulate Filter - DPF	07-Mar-2023 09:28:13	BHVYEQ	I	DON	509.31
02-Mar-2023 01	4,886	0	656218	25-065-004	Remove Cylinder	10-Mar-2023 10:11:34	BHVYEQ	I	DON	138.35
02-Mar-2023 01	4,886	0	656218	26-514-001	Weld Ears	15-Mar-2023 09:53:28	BHVYEQ	N	DON	322.27
02-Mar-2023 01	4,886	0	656218	31-514-002	Rotate Shanks or Teeth	16-Mar-2023 15:28:45	BHVYEQ	I	DON	189.50
02-Mar-2023 01	4,886	0	656218	34-032-002	Reseal Starter	14-Mar-2023 17:05:34	BHVYEQ	I	DON	473.62
02-Mar-2023 01	4,886	0	656218	34-065-020	Reseal Control Valve	02-Jun-2023 16:11:43	BHVYEQ	I	DON	1,050.75
02-Mar-2023 01	4,886	0	656218	38-100-PMC	Service C PMI	13-Jun-2023 09:54:09	BHVYEQ	P	DON	1,182.64
02-Mar-2023 01	4,886	0	656218	B3-049-002	Program ECM Module	04-Apr-2023 07:54:07	BHVYEQ	W	DON	0.00
10-Aug-2023 11	5,087	0	695680	06-100-PMA	Inspect A PMI	11-Aug-2023 08:12:15	BHVYEQ	P	DON	43.46

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost	
Unit No: N1073 - 2015 CAT 336FL XE											
10-Aug-2023	1	5,087	0	695680	03-514-002	Replace Shanks or Teeth	11-Aug-2023 06:13:10	BHVYEQ	E	DON	1,309.25
10-Aug-2023	1	5,087	0	695680	24-065-007	Repair Hoses & Fittings	11-Aug-2023 06:13:18	BHVYEQ	I	DON	74.96
10-Aug-2023	1	5,087	0	695680	02-002-044	Clean Cab - Complete	11-Aug-2023 06:13:13	BHVYEQ	N	DON	32.06
10-Aug-2023	1	5,087	0	695680	38-100-PMA	Service A PMI	11-Aug-2023 08:12:18	BHVYEQ	N	DON	255.69
10-Aug-2023	1	5,087	0	695680	03-111-002	Replace Roller	11-Aug-2023 08:12:45	BHVYEQ	I	DON	337.94
05-Oct-2023	0:	5,195	0	710446	03-049-004	Replace ECM Sensor	04-Dec-2023 07:04:06	TRK004	I	DON	924.00
19-Mar-2024	1	5,291	0	746863	02-330	Clean Excavator	27-Mar-2024 05:01:48	BWASH	Z	DON	801.54
19-Mar-2024	1	5,291	0	746863	OS-330	Out-Service Excavator	20-Mar-2024 17:03:33	BHVYEQ	Z	DON	357.23