

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
17-Mar-2016	0	0	237942	25-173-001	Remove Body or Bed	17-Mar-2016 13:16:13	BSETUP	M	DON	21.88
06-Apr-2016	0	0	254573	14-071	Install Body	06-Apr-2016 06:00:00	BTRUCK	C	DON	7,367.94
18-Apr-2016	0	0	241402	06-100-DOT	Inspect DOT Federal Inspection	04-May-2016 09:20:52	BTRUCK	P	DON	55.40
18-Apr-2016	0	0	241402	14-016-005	Install Chassis Spring - Rear	04-May-2016 07:41:19	BTRUCK	C	DON	585.20
18-Apr-2016	0	0	241402	21-079-002	Fabricate Headache Rack		BWELD	M	CAN	0.00
19-May-2016	0	0	245106	12-519-002	Refinish Rear Bumper	20-May-2016 13:31:36	BSETUP	C	DON	150.11
19-May-2016	0	0	245106	14-002-003	Install Running Boards / Step Tubes	20-May-2016 14:11:20	BSETUP	C	DON	84.82
19-May-2016	0	0	245106	14-002-063	Install Computer Stand / Dock	20-May-2016 10:28:07	BSETUP	C	DON	390.16
19-May-2016	0	0	245106	14-034-006	Install Warning Lamps - Special Application	24-May-2016 07:21:43	BSETUP	C	DON	368.94
19-May-2016	0	0	245106	14-052-003	Install Radio Equipment	20-May-2016 08:39:59	BSETUP	C	DON	1,221.97
19-May-2016	0	0	245106	14-052-014	Install Cellular Telephone Accessories	20-May-2016 06:07:39	BSETUP	C	DON	76.65
19-May-2016	0	0	245106	14-052-015	Install Power Inverter/Converter	20-May-2016 09:39:24	BSETUP	C	DON	282.31
19-May-2016	0	0	245106	14-053-004	Install Safety Equipment	31-May-2016 14:59:07	BSETUP	C	DON	120.96
19-May-2016	0	0	245106	14-053-005	Install Markings - Vehicle - Decals	19-May-2016 10:24:41	BSETUP	C	DON	149.02
19-May-2016	0	0	245106	14-053-014	Install Floor Mats	31-May-2016 14:58:56	BSETUP	C	DON	97.71
19-May-2016	0	0	245106	14-053-015	Install Tool Box	23-May-2016 07:27:01	BSETUP	C	DON	632.19
19-May-2016	0	0	245106	14-078-009	Install Mud Flaps and Hanger Brackets	23-May-2016 08:22:17	BSETUP	C	DON	111.76
19-May-2016	0	0	245106	14-078-012	Install Tie-Down - Tarpsaulin	24-May-2016 14:34:42	BSETUP	C	DON	153.38
19-May-2016	0	0	245106	14-079-002	Install Headache Rack	23-May-2016 12:15:37	BSETUP	C	DON	524.26
19-May-2016	0	0	245106	14-506-001	Install Fuel Tank	23-May-2016 10:58:24	BSETUP	C	DON	902.60
03-Jun-2016	1	154	246905	06-100-007	Inspect In-Service Inspection	21-Jun-2016 08:38:22	MPNSHP	C	DON	1,615.42
18-Jul-2016	14	2,973	256754	06-100-PMA	Inspect A PMI	18-Jul-2016 14:41:11	BVLOFC	P	DON	63.19
15-Aug-2016	0	6,022	262849	06-100-PMA	Inspect A PMI	15-Aug-2016 06:58:27	BTRUCK	P	DON	65.61
19-Sep-2016	1	9,866	266280	06-100-PMA	Inspect A PMI	19-Sep-2016 13:00:38	BTRUCK	P	DON	51.96
27-Oct-2016	0	13,944	270314	06-100-PMA	Inspect A PMI	27-Oct-2016 07:56:29	BVLOFC	P	DON	68.96
20-Dec-2016	1	18,029	270368	06-100-PMA	Inspect A PMI	20-Dec-2016 11:25:09	BVLOFC	P	DON	99.99
07-Feb-2017	1	23,875	276423	03-002-035	Replace Windshield Wiper & Washer	07-Feb-2017 14:38:14	BVLOFC	O	DON	56.60
07-Feb-2017	1	23,875	276423	03-041-007	Replace Filter - Outer	07-Feb-2017 14:37:16	BVLOFC	P	DON	37.87
07-Feb-2017	1	23,875	276423	06-100-PMA	Inspect A PMI	07-Feb-2017 14:39:32	BTRUCK	P	DON	98.81

Unit No: B2931 - 2016 F250 EXT CAB

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B2931 - 2016 F250 EXT CAB										
21-Mar-2017 0	28,442	0	282096	06-100-PMA	Inspect A PMI	21-Mar-2017 00:00:00	BVLOFC	P	DON	95.13
06-Jun-2017 1			315344	06-100-PMA	Inspect A PMI	06-Jun-2017 13:46:00	BVLOFC	P	DON	72.05
09-Aug-2017 1	39,695		300345	06-100-PMA	Inspect A PMI	13-Aug-2017 07:33:00	BVLOFC	P	DON	51.65
14-Aug-2017 0			301820	06-100-DOT	Inspect DOT Federal Inspection	25-Aug-2017 13:35:20	HARFLD	P	DON	77.47
06-Oct-2017 0	39,695		307810	06-100-PMA	Inspect A PMI	06-Oct-2017 13:28:00	BVLOFC	P	DON	51.65
15-Dec-2017 1	53,125		316343	06-100-PMA	Inspect A PMI	02-Jan-2018 10:52:38	BVLOFC	P	DON	51.65
15-Dec-2017 1	53,125		316343	03-041-007	Replace Filter - Outer	02-Jan-2018 10:52:35	BVLOFC	P	DON	40.39
02-Jan-2018 1	54,825		317760	03-013-011	Replace Anti-Lock Sensor Assembly	19-Jan-2018 07:43:33	BVLOFC	O	DON	282.35
02-Jan-2018 1	54,825		317760	03-033-003	Replace Spark Plugs	19-Jan-2018 07:43:30	BVLOFC	O	DON	300.59
03-Jan-2018 1	54,825		318057	03-017-001	Replace Tire - Pneumatic	03-Jan-2018 15:21:35	BTIRE	N	DON	1,224.00
26-Apr-2018 1	63,119		333090	03-013-001	Replace Front Brakes & Drums	26-Apr-2018 12:40:56	BVLOFC	O	DON	500.03
26-Apr-2018 1	63,119		333090	06-100-PMA	Inspect A PMI	26-Apr-2018 12:40:52	BVLOFC	P	DON	76.34
21-Jun-2018 1	66,504		340789	24-002	Repair Cab & Sheet Metal	10-Jul-2018 15:17:35	BVLOFC	A	DON	4,204.91
13-Sep-2018 1	73,277		351961	06-100-PMA	Inspect A PMI	24-Sep-2018 13:37:02	BVLOFC	P	DON	213.09
15-Nov-2018 1	77,599		360852	03-013-002	Replace Rear Brakes & Drums	04-Dec-2018 14:43:26	BVLOFC	I	DON	525.43
15-Nov-2018 1	77,599		360852	03-032-001	Replace Battery	04-Dec-2018 14:43:26	BVLOFC	I	DON	178.71
15-Nov-2018 1	77,599		360852	24-016-005	Repair Chassis Spring - Rear	04-Dec-2018 14:43:26	BVLOFC	O	DON	391.06
15-Nov-2018 1	77,599		360852	03-001-011	Replace Clutch Assembly - Compressor	04-Dec-2018 14:43:26	BVLOFC	O	DON	754.18
19-Dec-2018 0	80,758		365315	03-033-003	Replace Spark Plugs	20-Dec-2018 09:08:14	BVLOFC	I	DON	384.79
19-Dec-2018 0	80,758		365315	06-100-PMA	Inspect A PMI	20-Dec-2018 09:08:14	BVLOFC	P	DON	42.18
19-Apr-2019 0	90,492		381987	03-013-001	Replace Front Brakes & Drums	10-Jun-2019 11:18:11	BVLOFC	O	DON	739.45
19-Apr-2019 0	90,492		381987	03-015-004	Replace Steering Linkage	10-Jun-2019 11:18:11	BVLOFC	I	DON	355.88
19-Apr-2019 0	90,492		381987	03-016-004	Replace Stabilizer (Sway) Bar - Front	10-Jun-2019 11:18:11	BVLOFC	I	DON	354.16
19-Apr-2019 0	90,492		381987	09-015	Align Steering	10-Jun-2019 11:18:11	BVLOFC	I	DON	111.72
19-Apr-2019 0	90,492		381987	03-017-001	Replace Tire - Pneumatic	10-Jun-2019 11:18:11	BVLOFC	O	DON	1,158.15
19-Apr-2019 0	90,492		381987	03-015-012	Replace Steering Stability System	10-Jun-2019 11:18:11	BVLOFC	I	DON	99.06
12-Jun-2019 1	95,372		389876	03-017-001	Replace Tire - Pneumatic	12-Jun-2019 15:51:06	BVLOFC	O	DON	282.64
03-Jul-2019 00	98,459		393482	06-100-PMA	Inspect A PMI	03-Jul-2019 00:00:00	BVLOFC	P	DON	0.00
03-Jul-2019 00	98,459		393482	38-100-PMA	Service A PMI	03-Jul-2019 00:00:00	BVLOFC	P	DON	55.28

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B2931 - 2016 F250 EXT CAB										
03-Jul-2019 00	98,459		393482	38-001-001	Service Air Conditioning Assembly	03-Jul-2019 00:00:00	BVLOFC	O	DON	137.42
11-Nov-2019 1	113,379		412104	06-100-PMA	Inspect A PMI	11-Nov-2019 12:56:31	BTRUCK	P	DON	0.00
11-Nov-2019 1	113,379		412104	38-100-PMA	Service A PMI	11-Nov-2019 12:56:31	BVLOFC	P	DON	42.03
28-Jan-2020 0	125,932		428836	38-016-050	Service Alignment All Wheel	28-Jan-2020 06:28:00	BVLOFC	N	DON	111.72
28-Jan-2020 0	125,932		428836	38-100-PMA	Service A PMI	28-Jan-2020 06:26:00	BVLOFC	P	DON	56.65
09-Mar-2020 0	127,332		430581	06-100-PMA	Inspect A PMI	11-Mar-2020 16:05:00	TRK001	P	DON	2.71
09-Mar-2020 0	127,332		430581	38-100-PMA	Service A PMI	11-Mar-2020 16:00:00	TRK001	P	DON	174.45
31-Mar-2020 0	128,363		433644	03-017-001	Replace Tire - Pneumatic	21-Apr-2020 14:50:17	BTIRE	P	DON	1,089.95
01-May-2020 (130,902		438790	03-018-001	Replace Front Axle Hubs & Bearings	01-May-2020 06:20:05	BVLOFC	O	DON	861.65
01-May-2020 (130,902		438790	03-045-023	Replace Engine Belts	01-May-2020 06:20:05	BVLOFC	I	DON	184.69
01-May-2020 (130,902		438790	06-100-PMA	Inspect A PMI	01-May-2020 06:20:05	BVLOFC	P	DON	0.00
01-May-2020 (130,902		438790	03-033-003	Replace Spark Plugs	01-May-2020 06:20:05	BVLOFC	I	DON	400.53
01-May-2020 (130,902		438790	03-041-007	Replace Filter - Outer	01-May-2020 06:20:05	BVLOFC	P	DON	47.07
01-May-2020 (130,902		438790	38-100-PMA	Service A PMI	01-May-2020 06:20:05	BVLOFC	P	DON	67.11
01-May-2020 (130,902		438790	31-017-001	Rotate Tire - Pneumatic	01-May-2020 06:20:05	BVLOFC	P	DON	44.69
01-May-2020 (130,902		438790	38-025-001	Service Transfer Case Assembly	01-May-2020 06:20:05	BVLOFC	P	DON	325.36
01-May-2020 (130,902		438790	38-044	Service Fuel System	01-May-2020 06:20:05	BVLOFC	P	DON	269.40
01-May-2020 (130,902		438790	03-022	Replace Axles - Driven, Rear	01-May-2020 06:20:05	BVLOFC	I	DON	238.54
16-Jun-2020 0	135,920		445720	03-034-002	Replace Stop, Tail, Turn & License	16-Jun-2020 07:47:33	HARSHP	O	DON	40.38
09-Jul-2020 05	139,496		449578	03-001-013	Replace Evaporator Core	15-Jul-2020 12:15:24	BVLOFC	I	DON	2,404.09
09-Jul-2020 05	139,496		449578	03-002-035	Replace Windshield Wiper & Washer	15-Jul-2020 12:15:24	BVLOFC	I	DON	61.17
09-Jul-2020 05	139,496		449578	03-013-001	Replace Front Brakes & Drums	15-Jul-2020 12:15:24	BVLOFC	I	DON	1,087.57
09-Jul-2020 05	139,496		449578	03-033-002	Replace Distributor / Coil Pack	15-Jul-2020 12:15:24	BVLOFC	I	DON	334.30
09-Jul-2020 05	139,496		449578	03-034	Replace Lighting System	15-Jul-2020 12:15:24	BVLOFC	I	DON	52.78
09-Jul-2020 05	139,496		449578	03-034-004	Replace Clearance & Marker Lamps	15-Jul-2020 12:15:24	BVLOFC	I	DON	348.15
09-Jul-2020 05	139,496		449578	03-041-007	Replace Filter - Outer	15-Jul-2020 12:15:24	BVLOFC	P	DON	25.65
09-Jul-2020 05	139,496		449578	06-100-PMA	Inspect A PMI	15-Jul-2020 12:15:24	BTRUCK	P	DON	0.00
09-Jul-2020 05	139,496		449578	35-001	Diagnose Air Conditioning, Heating & Ventilati	15-Jul-2020 12:15:24	BVLOFC	O	DON	0.00
09-Jul-2020 05	139,496		449578	38-100-PMA	Service A PMI	15-Jul-2020 12:15:24	BVLOFC	P	DON	73.22

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B2931 - 2016 F250 EXT CAB										
01-Aug-2020 C	144,607		457258	06-100-PMA	Inspect A PMI	28-Aug-2020 09:46:43	BTRUCK	P	DON	0.00
01-Aug-2020 C	144,607		457258	31-017-001	Rotate Tire - Pneumatic	28-Aug-2020 09:46:43	BVLOFC	P	DON	11.17
01-Aug-2020 C	144,607		457258	38-100-PMA	Service A PMI	28-Aug-2020 09:46:43	BVLOFC	P	DON	62.04
01-Aug-2020 C	144,607		457258	24-017-001	Repair Tire - Pneumatic	28-Aug-2020 09:46:43	BVLOFC	I	DON	26.52
01-Aug-2020 C	144,607		457258	03-041-007	Replace Filter - Outer	28-Aug-2020 09:46:43	BVLOFC	P	DON	65.43
01-Aug-2020 C	144,607		457258	03-043-002	Replace Exhaust Manifold	28-Aug-2020 09:46:43	BVLOFC	I	DON	701.36
01-Aug-2020 C	144,607		457258	03-013-002	Replace Rear Brakes & Dnms	28-Aug-2020 09:46:43	BVLOFC	I	DON	2,461.89
13-Aug-2020 I	143,653		455902	03-017-002	Replace Tire - Semi-Pneumatic	13-Aug-2020 13:17:21	HARSHP	N	DON	147.29
29-Oct-2020 I	151,435		469393	38-100-PMA	Service A PMI	29-Oct-2020 10:49:32	BVLOFC	P	DON	49.47
29-Oct-2020 I	151,435		469393	24-052-001	Repair Cigar Lighter	29-Oct-2020 10:49:32	BVLOFC	O	DON	13.41
29-Oct-2020 I	151,435		469393	06-100-PMA	Inspect A PMI	29-Oct-2020 10:49:32	BTRUCK	P	DON	0.00
29-Oct-2020 I	151,435		469393	31-017-001	Rotate Tire - Pneumatic	29-Oct-2020 10:49:32	BVLOFC	P	DON	11.17
29-Oct-2020 I	151,435		469393	24-034-002	Repair Stop, Tail, Turn & License	29-Oct-2020 10:49:32	BVLOFC	O	DON	10.80
05-Feb-2021 O	156,330		486613	06-100-DOT	Inspect DOT Federal Inspection	24-Feb-2021 10:08:53	HARFLD	P	DON	189.74
22-Apr-2021 I	167,787		502180	06-100-PMA	Inspect A PMI	22-Apr-2021 11:59:41	SCHED	P	DON	0.00
22-Apr-2021 I	167,787		502180	38-100-PMA	Service A PMI	22-Apr-2021 11:59:44	MPNOFC	P	DON	163.17
19-May-2021 I	174,396		507733	06-100-PMA	Inspect A PMI	10-Jun-2021 09:05:57	SCHED	P	DON	0.00
19-May-2021 I	174,396		507733	38-100-PMA	Service A PMI	10-Jun-2021 09:05:57	SCHED	P	DON	55.64
19-May-2021 I	174,396		507733	24-025	Repair Transfer Case	10-Jun-2021 09:05:57	BVLOFC	O	DON	207.83
28-Jun-2021 O	180,503		515367	03-034-004	Replace Clearance & Marker Lamps	28-Jun-2021 07:59:14	BVLOFC	O	DON	8.98
28-Jun-2021 O	180,503		515367	06-100-PMA	Inspect A PMI	28-Jun-2021 07:59:14	SCHED	P	DON	0.00
28-Jun-2021 O	180,503		515367	31-017-001	Rotate Tire - Pneumatic	28-Jun-2021 07:59:14	BVLOFC	P	DON	30.08
28-Jun-2021 O	180,503		515367	38-100-PMA	Service A PMI	28-Jun-2021 07:59:14	SCHED	P	DON	89.98
23-Aug-2021 C	186,976		526750	06-100-PMA	Inspect A PMI	25-Aug-2021 14:28:47	SCHED	P	DON	0.00
23-Aug-2021 C	186,976		526750	38-100-PMA	Service A PMI	25-Aug-2021 14:28:47	SCHED	P	DON	117.54
28-Oct-2021 I	192,001		542540	38-100-PMA	Service A PMI	28-Oct-2021 11:07:17	BVLOFC	P	DON	78.15
28-Oct-2021 I	192,001		542540	03-017-001	Replace Tire - Pneumatic	28-Oct-2021 11:07:17	BVLOFC	O	DON	1,330.95
28-Oct-2021 I	192,001		542540	06-100-PMA	Inspect A PMI	28-Oct-2021 11:07:17	BVLOFC	P	DON	0.00
28-Oct-2021 I	192,001		542540	09-015	Align Steering	28-Oct-2021 11:07:17	BVLOFC	I	DON	167.04

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B2931 - 2016 F250 EXT CAB										
28-Oct-2021 11:07:17	192,001		542540	24-034-004	Repair Clearance & Marker Lamps	28-Oct-2021 11:07:17	BVLOFC	I	DON	45.94
10-Jan-2022 13:51:08	197,644		558042	03-018-001	Replace Front Axle Hubs & Bearings	10-Jan-2022 13:51:08	BVLOFC	P	DON	2,061.64
10-Jan-2022 13:41:07	197,644		558042	06-100-PMA	Inspect A PMI	10-Jan-2022 13:41:07	BVLOFC	P	DON	0.00
10-Jan-2022 13:51:08	197,644		558042	31-017-001	Rotate Tire - Pneumatic	10-Jan-2022 13:51:08	BVLOFC	P	DON	32.13
10-Jan-2022 13:51:08	197,644		558042	38-100-PMA	Service A PMI	10-Jan-2022 13:51:08	BVLOFC	P	DON	104.49
10-Jan-2022 13:51:08	197,644		558042	03-013-001	Replace Front Brakes & Drums	10-Jan-2022 13:51:08	BVLOFC	I	DON	535.30
22-Feb-2022 13:52:25	197,644		569015	06-100-PMA	Inspect A PMI	22-Feb-2022 13:52:25	BVLOFC	P	DON	0.00
22-Feb-2022 13:52:25	197,644		569015	38-100-PMA	Service A PMI	22-Feb-2022 13:52:25	BVLOFC	P	DON	113.88
28-Feb-2022 08:31:04	197,644		572161	95-063-003	Travel Transceiver - GPS Tracker	05-Mar-2022 08:31:04	SYRFLD	Q	DON	284.60
01-Mar-2022 17:38:27	197,644		576548	03-063-003	Replace Transceiver - GPS Tracker	22-Mar-2022 17:38:27	SYRFLD	Q	DON	332.10
30-Mar-2022 12:58:00	204,703		586967	06-100-PMA	Inspect A PMI	30-Mar-2022 12:58:00	BVLOFC	P	DON	0.00
30-Mar-2022 12:58:00	204,703		586967	38-100-PMA	Service A PMI	30-Mar-2022 12:58:00	BVLOFC	P	DON	137.57
29-Jun-2022 13:24:09	204,703		600058	06-100-DOT	Inspect DOT Federal Inspection	02-Jul-2022 13:24:09	ME0656	P	DON	156.84
12-Sep-2022 06:34:36	210,377		615395	03-001-013	Replace Evaporator Core	12-Sep-2022 06:34:36	BVLOFC	I	DON	2,524.86
12-Sep-2022 06:34:32	210,377		615395	03-018-001	Replace Front Axle Hubs & Bearings	12-Sep-2022 06:34:32	BVLOFC	I	DON	2,151.89
12-Sep-2022 06:34:46	210,377		615395	06-100-DOT	Inspect DOT Federal Inspection	12-Sep-2022 06:34:46	BVLOFC	P	DON	0.00
12-Sep-2022 06:34:12	210,377		615395	06-100-PMA	Inspect A PMI	12-Sep-2022 06:34:12	BVLOFC	P	DON	0.00
12-Sep-2022 06:34:27	210,377		615395	24-017-001	Repair Tire - Pneumatic	12-Sep-2022 06:34:27	BVLOFC	I	DON	44.38
12-Sep-2022 06:34:42	210,377		615395	24-034-004	Repair Clearance & Marker Lamps	12-Sep-2022 06:34:42	BVLOFC	I	DON	155.36
12-Sep-2022 06:34:21	210,377		615395	31-017-001	Rotate Tire - Pneumatic	12-Sep-2022 06:34:21	BVLOFC	P	DON	66.53
12-Sep-2022 06:34:50	210,377		615395	38-100-DOT	Service DOT Federal Inspection	12-Sep-2022 06:34:50	BVLOFC	P	DON	148.11
12-Sep-2022 06:34:17	210,377		615395	38-100-PMA	Service A PMI	12-Sep-2022 06:34:17	BVLOFC	P	DON	95.98
01-Dec-2022 10:37:40	210,377		636085	03-032-001	Replace Battery	01-Dec-2022 10:37:40	BVLOFC	B	DON	259.85
01-Dec-2022 10:37:40	210,377		636085	03-031-001	Replace Generator/Alternator	01-Dec-2022 10:37:40	BVLOFC	B	DON	887.57
01-Dec-2022 10:37:40	210,377		636085	20-010	Tow Chassis Group	01-Dec-2022 10:37:40	BVLOFC	B	DON	205.31
24-Dec-2022 11:57:10	210,377		640206	03-033-002	Replace Distributor / Coil Pack	24-Dec-2022 11:57:10	SYRFLD	B	DON	3,441.95
19-Dec-2022 11:04:00	225,933		654851	03-031-001	Replace Generator/Alternator	19-Dec-2022 11:04:00	BVLOFC	O	DON	920.88
01-Feb-2023 10:52:00	225,933		654846	24-017-001	Repair Tire - Pneumatic	01-Feb-2023 10:52:00	BVLOFC	O	DON	106.72
26-Apr-2023 09:02:49	231,090		670132	03-002-035	Replace Windshield Wiper & Washer	26-Apr-2023 09:02:49	BVLOFC	I	DON	50.98

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B2931 - 2016 F250 EXT CAB										
26-Apr-2023 0	231,090		670132	06-100-PMA	Inspect A PMI	26-Apr-2023 09:02:49	BVLOFC	P	DON	0.00
26-Apr-2023 0	231,090		670132	38-100-PMA	Service A PMI	26-Apr-2023 09:02:49	BVLOFC	P	DON	88.47
26-Apr-2023 0	231,090		670132	03-041-007	Replace Filter - Outer	26-Apr-2023 09:02:49	BVLOFC	I	DON	29.74
18-May-2023 1	231,090		675446	03-017-001	Replace Tire - Pneumatic	24-May-2023 10:44:08	SYRFLD	B	DON	904.26
26-Jun-2023 1	231,090		684102	03-017-001	Replace Tire - Pneumatic	28-Jun-2023 06:56:06	SYRFLD	O	DON	1,854.50
18-Aug-2023 1	238,486		698039	03-041-007	Replace Filter - Outer	18-Aug-2023 11:12:07	BVLOFC	I	DON	21.24
18-Aug-2023 1	238,486		698039	06-100-PMA	Inspect A PMI	18-Aug-2023 11:12:07	BVLOFC	P	DON	0.00
18-Aug-2023 1	238,486		698039	38-100-PMA	Service A PMI	18-Aug-2023 11:12:07	BVLOFC	P	DON	84.22
09-Nov-2023 C	238,486		719981	03-044-003	Replace Fuel Pump	13-Nov-2023 08:42:36	SYRFLD	B	DON	1,051.70
09-Nov-2023 C	238,486		719981	19-044-003	Wire/Rewire Fuel Pump	13-Nov-2023 08:43:58	SYRFLD	B	DON	174.92
27-Nov-2023 C	238,486		724386	06-001	Inspect Air Conditioning, Heating & Ventilating	21-Dec-2023 14:23:31	SYRFLD	O	DON	174.92
27-Nov-2023 C	238,486		724386	03-001-010	Replace Compressor Assembly - Air Cond		SYRFLD	B	WR	957.36
27-Nov-2023 C	238,486		724386	03-044-003	Replace Fuel Pump	07-Dec-2023 14:28:53	SYRFLD	B	DON	676.04
08-Jan-2024 0:	238,486		730900	03-042-012	Replace Clamps and Hoses	09-Jan-2024 08:41:48	SYRFLD	B	DON	272.41
08-Jan-2024 0:	238,486		730900	06-100-DOT	Inspect DOT Federal Inspection	08-Jan-2024 08:40:00	SYRFLD	P	DON	262.38
08-Jan-2024 0:	238,486		730900	06-100-PMA	Inspect A PMI	09-Jan-2024 08:42:02	SYRFLD	P	DON	87.46
08-Jan-2024 0:	238,486		730900	06-100-PMB	Inspect B PMI	10-Feb-2024 10:43:06	SYRFLD	P	DON	87.46
08-Jan-2024 0:	238,486		730900	38-100-PMA	Service A PMI	10-Feb-2024 10:43:06	SYRFLD	P	DON	137.60
08-May-2024 1	254,705		758359	06-100-009	Inspect Safety Check	09-May-2024 07:32:04	BTRUCK	P	DON	26.49
30-May-2024 1	254,705		762890	25-051	Remove General Accessories	03-Jun-2024 11:41:12	BSETUP	Z	DON	492.56
30-May-2024 1	254,705		762890	02-002	Clean Cab & Sheet Metal	06-Jun-2024 09:42:51	BSETUP	Z	DON	230.75

Unit No: B2931

Count: 166

65,089.97